# McDonnell Douglas Helicopter Company SERVICE INFORMATION NOTICE

DATE 23 Jan 1976

FAA APPROVED

MANDATORY MANDATORY MANDATORY

SUBJECT: MODIFICATION FOR SEATING AND BELTS FOR (4) KIT INSTALLATION,

PN 369H90035-501 - ADDITION OF HEAD AND BACK RESTRAINT PANELS

MODELS AFFECTED:

All Model 500 Series Helicopters with Subject Seating and

Belts for (4) Kit Installed Prior to Date of this Notice

All Subject Kits in Spares Inventory Prior to Date of this

Notice

TIME OF COMPLIANCE:

Shall be accomplished prior to next flight with aft facing

seat(s) occupied

Shall be accomplished at installation of subject kit(s) in

Spares Inventory

PREFACE:

The information given in this Service Information Notice lists a procedure for installing head and back restraint panels for aft-facing occupants utilizing the seating and belts for (4) on the floor.

Installation of the restraint panels lifts the requirement for placard installation per FAA Airworthiness Directive 75-09-17, Amendment 39-2191 effective May 2, 1975; and permits take off and landing with aft facing seats occupied.

### Reference

500 Series - Basic HMI, Issued 1 October 1972; Revision No. 5, 15 June 1975 500 Series - HMI Appendix A, Issued 1 October 1972; Revision No. 4, 15 Dec 1974

Product Support Department

NOTICE NO. HN-91 DATE: 23 Jan 1976

PAGE: 2 of 4

# PARTS LIST

Nomenclature	Part No.	Qty	Mfr
Restraint Panel Assy (RH) Restraint Panel Assy (LH) Bracket Assy Bracket Assy Bracket Assy Rivet Rivet	369H90035-19 369H90035-17 369H90035-9 369H90035-7 369H90035-5 MS20470AD4 NAS1398B4-2	1 1 4 2 2 A/R	Mfr HH HH HH HH Commercial
Screw Washer	NAS514P1032-8 5724-17	8 8 8	Commercial Commercial Commercial

# TOOLS AND EQUIPMENT

Drill motor - portable
Drill bit - #30
Drill bit - 0.217/0.229 inch diameter
Rivet gun - For Driven Rivets
Hand Riveter #G-36 and Puller #H-611

Cherry Rivet Div Townsend Co. 1224 E. Warner Santa Ana, CA

# MODIFICATION PROCEDURE

a. Remove aft compartment cushion seats.

## NOTE

Step b not applicable to HM helicopters.

- b. Remove shoulder straps from shoulder harness fitting, LH and RH sides of Station 78.50 canted frame bulkhead; remove cap fitting from LH and RH shoulder harness fitting; remove aft compartment forward trim panel.
  - c. Remove or displace aft compartment seat belt assemblies.
- d. Install 369H90035-9 bracket assemblies (two each LH and RH sides) on Station 78.50 canted frame bulkhead lower section at WL 22.45 and BL 8.25 and 19.25. Use MS20470AD4 rivets. (See Figure 1, Detail C.)
- e. Install 369H90035-7 bracket assemblies (one each LH and RH sides) on channel of canted frame bulkhead upper section at WL 45.30 and BL 15.50. Use NAS1398 B4-2 rivets. (See Figure 1, Detail B.)

NOTICE NO. HN-91 DATE: 23 Jan 1976

PAGE: 3 of 4




Figure 1. Installation of Head and Back Restraint Panels and Attach Hardware

NOTICE NO. HN-91 DATE: 23 Jan 1976

PAGE: 4 of 4

- f. Install 369H90035-5 bracket assemblies (one each LH and RH sides) on same channel at WL 45.30 and BL 8.50. Use NAS1398B4-2 rivets.
- g. Drill four 0.217/0.229 inch diameter holes in aft compartment forward trim panel, as applicable; and in 369H90035-17 and -19 restraint panel assemblies. Locate holes from installed 369H90035-5, -7 and -9 bracket assemblies.
  - h. Reinstall aft compartment forward trim panel, as applicable.
- i. Install 369H90035-17 and -19 restraint panel assemblies on bracket assemblies, using NAS514P1032-8 screws and 5724-17 washers.
  - j. Reinstall cap fittings on shoulder harness fittings, as applicable.
  - k. Reinstall aft compartment cushion seats and belt assemblies.
- 1. Remove placard, "DO NOT OCCUPY FOR TAKEOFF AND LANDING", above aft facing seat cushion, LH and RH sides.
- m. Record compliance with this Service Information Notice in Compliance Record of helicopter Log Book.

### WEIGHT AND BALANCE DATA

ADD: 14.1 lb at 85.2 inch arm (369H90035-17 and -19 Restraint Panel Assemblies)

0.6 lb at 81.3 inch arm (369H90035-9 Bracket Assemblies)

0.5 lb at 88.1 inch arm (369H90035-5 and -7 Bracket Assemblies)