

## SERVICE BULLETIN

**DATE: 23 AUGUST 1971** 

PAGE 1 OF 4

MANDATORY MANDATORY MANDATORY MANDATORY

### NEW PRESSURE-ACTUATED SWITCH – AUTOMATIC ENGINE REIGNITION KIT INSTALLATION, P/N 369H90118-501 OR P/N 369H90140

### 1. PLANNING INFORMATION

### A. MODELS AFFECTED:

All 369H Series Helicopters Equipped With Subject Automatic Engine Reignition Kits

#### **B. PREFACE:**

The information given in this Service Information Notice lists a procedure for replacing the existing P/N 369H92025-3 pressure-actuated switch on the automatic engine reignition kit installation with a new P/N 369H92040 switch, to improve reliability and operating performance of the engine relight system.

#### C. TIME OF COMPLIANCE:

Shall be accomplished when replacement of pressure switch is required.

#### D. WEIGHT AND BALANCE:

Weight and balance not affected

#### E. REFERENCE:

500 Series - Basic Handbook of Maintenance Instructions, Revised 1 June 1971 500 Series - HMI Appendix A, Revised I June 1971



**DATE: 23 AUGUST 1971** 

## SERVICE BULLETIN

PAGE 2 OF 4

MANDATORY MANDATORY MANDATORY MANDATORY

#### F. PARTS LIST:

REPLACEMENT PARTS/SUPPLIES			
Nomenclature	Part No.	Qty.	Source
Switch, Pressure–actuated	369H92040	1	HTC -AD
Packing	NAS617-3	1	Commercial
Splice, Knife	32445	4	Amp Inc.
Silicon Tubing, Varglass	No. 4, H–A–1	A/R	Varflex Corp.
Silicon Tubing, Varglass	No. 3/8, H–A–1	A/R	Varflex Corp.
Cord, Lacing	T-3333	A/R	General Cable Corp.

#### 2. PROCEDURE

- a. Check that all electrical power is OFF; ensure that BATT-OFF-EXT switch is in OFF position.
- b. Disconnect battery.
- c. Open engine access doors.

**NOTE:** Note hazard label on exciter.

- d. Remove ignition exciter assembly, as follows, to gain access to work area:
  - 1. Carefully disconnect spark ignition lead from ignition exciter.
  - 2. Disconnect wire lead from exciter terminal.
  - 3. Remove hardware securing exciter from engine.
- e. Cut existing wiring from P302 connector to existing 369H92025-3 (S-10) pressure actuated switch. (See Figure 1)
- f. Remove switch from ANF783C3 tee; discard switch.
- g. Install new 369H92040 pressure switch (S-10) on tee; use new NAS617-3 packing.

**NOTE:** Fire sleeves are provided and must be installed only on new switches having vendor (Meletron) serial numbers 1 through 132. Secure sleeve with Cres safety wire as shown in Figure 1.

- h. Splice new pressure switch lead wires to P302 connector wires as shown; tie No. 4 silicone tubing over splices. Cover full length of wiring from P302 connector to S-10 switch with No. 3/8 silicone tubing.
- i. Reinstall ignition exciter assembly; reconnect wire lead and spark igniter lead assembly to exciter. Loosen heater/engine tubing as required. Note hazard label on exciter.
- j. Connect battery.



## **SERVICE BULLETIN**

**DATE: 23 AUGUST 1971** 

PAGE 3 OF 4

MANDATORY MANDATORY MANDATORY MANDATORY

k. Perform the following ground function check of the automatic engine re-light system:

#### NOTE:

- Ensure that Auto-Reignition toggle switch is in OFF position before manually starting engine by normal procedures.
- Prior to check of automatic reignition system, bleed torque gage pressure lines. Also, pressure and leak test lines between engine and torque gage at 200 psi; refer to Section 17 of Basic HMI.
- If amber RE-IGN light illuminates when key switch is set to ON position, press face of indicator module to extinguish amber light.
- 1. Start engine and set torque pressure at approximately 40 psi.
- 2. Set toggle switch to ON position; the green ARMED light will illuminate, indicating that the system is m the armed mode.
- 3. Reduce engine torque pressure below 25 psi; the amber RE-IGN light will illuminate, indicating that the ignition exciter is energized.
- 4. Increase engine torque pressure to approximately 40 psi; press and release face of indicator module to extinguish amber RE-IGN light.
- 5. Set Auto Re-Ignition toggle switch of OFF position. 6. Shut down engine; close engine access doors.
- l. Record compliance with this Service Information Notice in Compliance Record of helicopter Log Book.



**DATE: 23 AUGUST 1971** 

# **SERVICE BULLETIN**

PAGE 4 OF 4

MANDATORY MANDATORY MANDATORY MANDATORY




Figure 1. Installation - 369H92040 Pressure-Actuated Switch, Automatic Engine Reignition Kits