



TECHNICAL BULLETIN

DATE: 8 DECEMBER 1980
PAGE 1 OF 3

REWORK OF STATIC PRESSURE TUBE INSTALLATION TO MINIMIZE ALTIMETER NEEDLE OSCILLATION

1. PLANNING INFORMATION

A. MODELS AFFECTED:

All 500 Models 369H Series Helicopters

B. PREFACE:

The information given in this Service Information Notice lists a procedure for rework of the hardware connecting the crossover tube between the altimeter and airspeed indicators on the instrument panel to reduce needle bounce. The rework consists primarily of removing the existing 369H6610-3 plug from the connector at the airspeed indicator and installing a new 369H6610-23 plug in the existing tee at the altimeter indicator.

C. TIME OF COMPLIANCE:

At owners and operators discretion

D. FAA APPROVAL:

FAA/DER APPROVED 17 December 1980

E. WEIGHT AND BALANCE:

Weight and balance not affected

F. REFERENCE:

500 Series - Basic HMI, Issued I October 1972, Revision No. 7, 15 December 1976

G. PARTS LIST:

PARTS LIST			
Nomenclature	Part No.	Qty.	Source
Plug	369H6610-23	1	HH

TECHNICAL BULLETIN

2. REWORK PROCEDURE

- a. Check that all electrical power is OFF.
- b. Remove instrument panel fairing and hood, per Basic HMI.
- c. Disconnect drain tube from 369H6628 tee at altimeter indicator. (See Figure 1.)
- d. Press fit new 369H6610-23 plug into tee as shown, reconnect drain tube to tee. (See View B.)
- e. Disconnect crossover tube from connector at airspeed indicator.
- f. Remove existing -3 plug from 369R6610-11 or -21 union assembly.
- g. Reconnect crossover tube to connector at airspeed indicator.
- h. Reinstall instrument panel fairing and hood.
- i. Perform flight test to check instrument operation.

TECHNICAL BULLETIN

DATE: 8 DECEMBER 1980
PAGE 3 OF 3




Figure 1. Rework of Static Pressure Tube Installation