



CHK LET	REVISION	BY	CHK APPD
A	1091-2 FUSE WAS S1091-1	LEW	10/25
B	BY REV: 5-1317N2 WAS 5-1317N1 ERRR 10947	PER	11/15/69
C	BY REV: ADD DETAIL A, 5-1091-1 & 5-1090-22; SER SER(SR7310)	LEW	11/27/72

INACTIVE EFF THRU SER 33701462



WIRE CODE NO	GA	MATERIAL	LG	TERMINALS	SERIALS
K-DC-20		S1091-2			
K-DC-20		SOLDER			
K-DC-120		S1091-1B			

WIRE TABLE		TITLE	
NAME	DATE	DATE	
HARDEN	12/2/64		
GROUP			
CHECK	P. J. ...	11/15/69	
PROJ	11/15/69	11/15/69	
SUPERVISOR			

CESSNA AIRCRAFT CO COMMERCIAL AIRCRAFT DIVISION WICHITA, KANSAS

WIRING DIAGRAM —
CLOCK

1570000

REV C PAGE 103

PART NO	DESCRIPTION	INSTALLED ON
5 S-1090-22	FUSE HOLDER	
4 S-1091-1	FUSE	
3 S1090-1B	FUSE HOLDER	
2 S1091-2	FUSE	
1 S1091N2	CLOCK ASSY	

EQUIPMENT TABLE