



# SERVICE MANUAL CHANGE NOTICE

REFERENCE MANUAL NUMBER: D2500-13

SMCN #77-14  
DATE: June 27, 1977

MANUAL TITLE: SUPER SKYMASTER SERIES 1965 THRU 1973

TO: ALL ZONES AND DEALERS

FROM: CUSTOMER SERVICES DEPARTMENT

CORRECT YOUR SERVICE MANUAL AS SHOWN BELOW.

PAGE NUMBER	PARAGRAPH NUMBER	DESCRIPTION OF CHANGES
2-1	2-4	After the third sentence, insert the following: Beginning with aircraft Serials 33701549, F33700064, P3370139 and FP33700009 the jack points are to be installed just outboard of the wing strut, at W.S. 66.35 in rib assembly just aft of the front spar.
5-77	5-218	The following NOTE applies to the power pack secondary relief valve installation.  NOTE  To prevent drifting of the secondary relief valve setting, it is recommended that a new adjusting plug be used, and/or that the plug be staked in position (in 2 places 180° apart on the valve body), after the final adjustment is made.