



SL369H-148
SL369E-081

SL369D-128
SL369F-073

SERVICE LETTER

DATE: 12 AUGUST 2014
PAGE 1 OF 2

INSPECTION OF THE TAIL ROTOR STOP

MD Helicopters has received field reports of cracks on the tail rotor stop, Part No. (PN) 369H5307-7. This service letter is issued to remind owners and operators of the importance of the daily preflight examination of the tail rotor (ref. Procedure 4-1, Preflight Requirements, Tailboom / Tail Rotor, of the applicable RFM; and CSP-HMI-2, Section 05-00-00, Checks/Inspections, Procedure 3.A.(2)). The tail rotor stop is made of molded synthetic rubber (SAE AMS3208). A complete and thorough visual inspection of all tail rotor components for damage and installation is necessary.

For further assistance, contact the Field Service Department at MDHI, Mesa, Arizona. Telephone 1-800-388-3378 or (480) 346-6387. DATAFAX: (480) 346-6813.

SL369H-148
SL369E-081

SL369D-128
SL369F-073



SERVICE LETTER

DATE: 12 AUGUST 2014
PAGE 2 OF 2

This page intentionally left blank!