

*McDonnell Douglas  
Helicopter Company*

NOTICE NO. HN-66  
DATE 25 March 1974  
PAGE 1 OF 4

**SERVICE INFORMATION NOTICE**

FAA APPROVED

MANDATORY

MANDATORY

MANDATORY

SUBJECT: INSPECTION OF 369A2515-3 FRAME AND BATTERY

MODELS AFFECTED: All 369H Series Helicopters

TIME OF COMPLIANCE: Part I. On a onetime basis within next 100 hours of Helicopter Operation.  
Part II. If required per the Inspection Criteria of Part I.

PREFACE: Instances of interference between the subject frame and the battery have been observed in the field.

This Service Information Notice provides procedures for a one-time inspection of the frame and corrective action should the interference exist.

REFERENCE

269 Series Basic HMI Issued 1 April 1973, revised by Revision #1, dated 1 October 1971

Product Support Department

*McDonnell Douglas  
Helicopter Company*



NOTICE NO. HN-66  
DATE 25 March 1974  
PAGE 3 of 4

- c. Re-install battery and secure battery compartment.
- d. Record compliance with this Service Information Notice in Compliance Record of Helicopter Log Book.

**WEIGHT AND BALANCE DATA**

Weight and Balance not affected.




Figure 1. Fuselage Structure, Battery Location