



HL-121

SERVICE LETTER

DATE: 27 SEPTEMBER 1991
PAGE 1 OF 1

TO: All owners and operators of McDonnell Douglas Helicopter Company (MDHC) 369H Series helicopters, including the 369A (OH-6A) series helicopter.

OBSERVATION OF 369A1010(BSC) AND -3 MAIN ROTOR HUB HOISTING EYE BOLTS

MDHC has received a report from the field indicating that a 369A1010 main rotor hub hoisting eye bolt fractured. The bolt is one of four used to hoist the main rotor hub or helicopter and one of eight bolts used for transmitting engine torque to the main rotor hub.

Any operator experiencing an eye bolt fracture for unknown cause should remove and replace it. Also, MDHC is requesting that operators report any such experience to the MDHC Field Service Department.

A handwritten signature in black ink, appearing to read 'John Reagan'.

John Reagan, Manager
MD500 Customer Support Dept.
McDonnell Douglas
Helicopter Company
Product Support Department