



HL-106

SERVICE LETTER

DATE: 1 JULY 1988
PAGE 1 OF 1

TO: ALL OWNERS AND OPERATORS OF MCDONNELL DOUGLAS-HELICOPTER COMPANY
369H SERIES HELICOPTERS AND 369A (OH-6A) SERIES HELICOPTERS.

RECOMMENDED REPLACEMENT INTERVAL FOR 369H5655-3/-5 OIL COOLER BEARINGS AND 369H5648 OIL COOLER BELT.

The recommended replacement interval of the 369H5655-3/-5 oil cooler blower bearings and 369H5648 oil cooler blower belt has been increased from 900 hours to 1200 hours. This change to the recommended replacement interval is effective immediately.

NOTE: Replacement is not mandatory but is strongly recommended by MDHC, regardless of the condition of the components listed above at the interval specified.

A handwritten signature in black ink, appearing to read 'Cary Brown'.

Cary Brown, Manager,
Product Support Department
McDonnell Douglas
Helicopter Company