


PUBLICATION INDEXES

for
**HELICOPTER MODEL
369H (500C)**

**Technical Manuals Index
Service Bulletins Index
Technical Bulletins Index
Service Letters Index**



*MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734*

The hard copy distribution of publications, to subscribers of the MDHI Technical Manuals in paper format (hard copy), can take 90 days or more from the publication date of the document

Current indexes are available at: www.mdhelicopters.com

This page intentionally left blank!



MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

MODEL 369H (500C) HELICOPTER TECHNICAL MANUAL INDEX

* Complete Reissue - Supersedes All Previous Issues and/or Reissues.

Reprint - This Manual Has Been Reprinted, New Orders For This Manual Will Contain This Revision And All Prior Revisions And Reissues. Prior revisions will no longer be available.

A complete Pilot's Flight Manual for the 369H Helicopter consists of the following publications and binders:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------|--|--------------|--------------|---|--|
| CSP-HE/HS-1 | 369HE/HS Owners Manual This manual now applies to 369HM SN 010M thru 0214M, 0220M thru 0231M, 0233M thru 0238M, and 0244M and subsequent. | Original | 13 Jul 1998* | Rev 1 Rev 2 Rev 3 Rev 4 Rev 5 Rev 6 Rev 7 Rev 8 Rev 9 | 12 Nov 1998 25 Feb 2000 22 May 2000 10 Oct 2000 22 Mar 2001 4 Oct 2006 21 Mar 2007 09 Mar 2009 30 Sep 2010 |

A complete Handbook of Maintenance Instructions Set for the 369H Series Helicopter consists of the following publications and binders:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------|--|--------------|--------------|--|--|
| CSP-A-1 | Price Catalog | Reissue | 01 Jul 2010* | | |
| CSP-A-2 | Warranty Manual | Reissue | 23 Oct 2007 | | |
| CSP-A-3 | Corrosion Control Manual | Original | 09 Feb 1981 | TR 93-001 | 30 Jul 1993 |
| CSP-H-2 | Basic Handbook of Maintenance Instructions (Basic HMI) | Original | 15 Sep 1981* | Rev 1 Rev 2 Rev 3 Rev 4 Rev 5 Rev 6 Rev 7 Rev 8 Rev 9 Rev 10 Rev 11 Rev 12 Rev 13 Rev 14 Rev 15 Rev 16 Rev 17 Rev 18 Rev 19 Rev 20 Rev. 21 TR09-001 | 15 Jun 1985 14 Mar 1988 15 Jan 1989 01 Nov 1989 15 Jun 1990 01 Jul 1991 15 Oct 1992 13 Sep 1993 02 Mar 1994 05 Apr 1994 27 Apr 1994 10 Feb 1995 23 Aug 1996 19 May 2000 18 Aug 2000 16 Feb 2001 15 May 2001 29 Jan 2003 22 Jun 2005 22 Nov 2005 25 Apr 2007 27 Oct 2009 # |
| CSP-H-3 | Optional Equipment Manual (Basic HMI Appendix A) | Reissue 2 | 15 Oct 1982 | Rev 1 TR 93-001 | 15 Apr 1993 26 Jul 1993 # |
| CSP-H-4 | Periodic Inspections, Overhaul and Retirement Schedule and Weight and Balance Procedure (Basic HMI Appendix B) | Reissue 5 | 17 Nov 1999* | Rev 1 Rev 2 Rev 3 Rev 4 Rev. 5 TR10-001 TR11-001 | 14 May 2001 30 Jan 2003 25 Jun 2003 22 Apr 2004 25 Apr 2007 22 Dec 2010 04 Jan 2011 |

Current indexes are available at: www.mdhelicopters.com



| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------|---|--------------|-------------|---|--|
| CSP-H-5 | Component Overhaul Manual (Basic HMI Appendix C) | Original | 01 Apr 1976 | Rev 1 Rev 2 Rev 3 Rev 4 Rev 5 Rev 6 Rev 7 Rev 8 Rev 9 Rev 10 Rev 11 Rev 12 TR08-001 TR11-001 | 01 Aug 1976 15 Apr 1981 15 Mar 1982 15 Jul 1989 01 Apr 1990 # 31 Jul 1992 28 Apr 1995 23 Jun 1997 31 Jan 2003 15 Sep 2003 21 Jun 2005 28 Jul 2007 27 Sep 2008 28 Jan 2011 |
| CSP-H-6 | Structural Repair Manual (Basic HMI Appendix D) | Reissue 1 | 01 Oct 1973 | Rev 1 Rev 2 | 01 Oct 1973 30 Sep 1992 # |
| CSP-H-7 | Illustrated Parts Catalog (IPC) | Reissue 8 | 01 Sep 1980 | Rev 1 Rev 2 Rev 3 Rev 4 Rev 5 Rev 6 | 15 Aug 1988 17 Mar 1989 15 Sep 1989 16 Mar 1992 30 Sep 1993 11 Nov 1994 # |
| CSP-H-8 | Illustrated Optional Accessories and Modification Kit Catalog (IKC) | Reissue 2 | 01 Sep 1978 | Rev 1 | 09 Nov 1990 # |
| CSP-RLB | Rotorcraft Log Book | Original | 01 Dec 1994 | Rev 1 Rev 2 Rev 3 Rev 4 | 18 Apr 1997 17 Feb 2000 01 Jun 2001 31 May 2002 |

BINDERS

| | | | | | |
|--|--------------------|--|--|--|--|
| | B1 BINDER - 4" HMI | | | | |
| | B2 BINDER - 4" IPC | | | | |
| | B4 BINDER - 4" N&L | | | | |
| | B5 BINDER - PFM | | | | |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

MODEL 369H (500C) HELICOPTER
SERVICE BULLETIN INDEX

NOTE

As Service Information Notices are re-issued, they will be identified as Bulletins using the helicopter model designation as the prefix.

Service Bulletins are service information notices which are mandatory. Service Bulletins may require the performance of maintenance and/or alteration for compliance.

SERVICE BULLETINS

Table with 4 columns: 369H SB369H-OR HN-, SUBJECT, Date ISSUED, BORDER. Contains 28 rows of service bulletin details.

Current indexes are available at: www.mdhelicopters.com

SERVICE BULLETINS (CONT.)

| 369H SB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|---|----------------|--------|
| 73 | Inspection – Main Rotor Blade Trailing Edge (Ref. FAA AD 74-20-04) | 19 Aug 1974 | RED |
| 74.2 | Installation of Aluminum Type Main Rotor Blade Pendulum Weight Vibration Absorber Assembly PN 369N2697 | 29 Sep 1975 | RED |
| 75 | Rework or Replacement – Fuel Cell Assemblies PN 369H8101-3, -5 and 369A8102-3, -5 | 19 Aug 1974 | RED |
| 79.1 | Re-greasing Double Row Bearing – Main Rotor Swashplate Bearing Assembly PN 369A7003-3 | 24 Sep 1982 | RED |
| 82.1 | Inspection/Repair, Aft Fuselage Skin Cracks | 26 Sep 1975 | RED |
| 83 | Inspection – Root Fitting of Metal Tail Rotor Blades PN 369A1613-Basic and -3 (Ref. FAA AD 75-10-04) | 15 Apr 1975 | RED |
| 86 | Tail Rotor Drive System Inspection – Installation of Tail Rotor Drive Shaft PN 369A5518-601 and Bungee Assembly Associated With Metal Tail Rotor Blades and Indexing of all Helicopter Tail Rotor Drive Shafts (Ref. FAA AD 75-22-03) | 28 Apr 1975 | RED |
| 87 | Inspection and Relocation of Fuel Filter Pressure Switch PN 369H8144 | 23 Jun 1975 | RED |
| 88 | Inspection – Fiberglass Tail Rotor Blades PN 369A1710-Basic, -9, -11 369A6120, 369A1607 and 369CSK22 (Ref. FAA AD 75-22-04) | 28 Aug 1975 | RED |
| 91 | Modification for Seating and Belts for (4) Kit Installation, PN 369H90035-501 Additional of Head and Back Restraint Panels (Ref. FAA AD 75-09-17) | 23 Jan 1976 | RED |
| 95 | Inspection and Repair – Adjustable Upper Engine Mount Assemblies PN 369H8016-1 and -2 | 26 Apr 1976 | RED |
| 96 | Engine Air Particle Separator Filter Assembly Kit Installation PN 369H90148 Basic and -501 Configurations – Installation of New Aft Screen Assembly PN 369H90157 | 10 May 1976 | RED |
| 97 | Relocation – Outside Air Temperature (OAT) Indicator PN 369H4515 (Modification Kit PN M30301) | 18 Jun 1976 | RED |
| 98 | Potting of N2 Governor Control PN 369A4580 – Pilot's and Co-pilot's Collective Pitch Stick Assemblies | 18 Jun 1976 | RED |
| 99 | Inspection – Tail Rotor Pitch Control Link Assemblies PN 369A1807-Basic and -5 | 18 Jun 1976 | RED |
| 101 | Field Replacement of Lock Fitting – Ground Handling Wheel Assemblies PN 369A9905 (AER-BEA PN AB 2387) | 10 Aug 1976 | RED |
| 102.3 | Inspection of PN 369A2001-601 – Shock-Mounted Stabilizer Strut Assembly and Possible Replacement of 369A2130 Damper Plunger (Ref. FAA AD 76-19-03) | 24 Dec 1976 | RED |
| 103.2 | Rework of PN 369A7120 – Longitudinal Friction Guide Link, Cyclic Pitch Control Installation | 12 Sep 1977 | RED |
| 108 | Inspection – Attachment Hardware, Main Rotor Pitch Control Rods to Pitch Housing Assembly | 24 Dec 1976 | RED |
| 109 | 100 Hour Inspection – Main Rotor Hub Lead-Lag Links, PN 369A1234-Basic, -7, 80-369H1234, and Lead-Lag Link Assembly PN 369H1203 | 24 Dec 1976 | RED |
| 110 | Inspection – Tail Rotor Drive Shaft Damper PN 369A5506 | 24 Dec 1976 | RED |
| 111.1 | Inspection of PN 369A3511-15 and 369A3511-17 – Tailboom Bracket Assemblies, Tail Rotor Transmission Attachment | 12 Sep 1977 | RED |
| 114 | Replacement of Tavco PN 23111357 Solenoid Valve, Float Inflation System – Emergency Float Assemblies Hughes PN 369H92036-1/-2 (Ref. FAA AD 77-09-01) | 15 Apr 1977 | RED |
| 116 | Wiring Modification Kit (PN M50450) Automatic Engine Re-ignition Kit PN 369H90118-505, -507, -509, -511 | 08 Aug 1977 | RED |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

SERVICE BULLETINS (CONT.)

| 369H SB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|---|----------------|--------|
| 117 | Inspection and Modification of Oil Cooler Duct PN 369H8301 or 710108 Kit Installation PN M50451 | 22 Jul 1977 | RED |
| 118.2 | Overrunning Clutch Assembly PN 369A5350-601 - Inspection of PN 3695350-11 Clutch Assembly; PN 369A5361 Ball Bearing, and PN 369A5368 Seal (Ref. FAA AD 77-21-04) | 27 Oct 1978 | RED |
| 121 | Inspection - PN 369H90085 Litter Door Installation | 30 Nov 1977 | RED |
| 124 | Engine Compressor Water Wash Kit Installation PN 369A92537 - Inspection and Replacement of Rivets | 14 Apr 1978 | RED |
| 128.1 | Inspection and Rework of Tail Rotor Hub PN 369A1725-Basic and 369A1725-5 (Ref. FAA AD 78-26-04) | 08 Dec 1978 | RED |
| 130 | Periodic Inspection - Battery Over-Temperature Warning System | 10 Jan 1979 | RED |
| 131.1 | Replacement of PN 369A1602 Tail Rotor Drive Fork Hinge Bolt and PN 369A1603 Nut, New Assembly Procedure for Tail Rotor Hub and Drive Fork Unit, Periodic Check of Flapping Bolt Preload | 02 Sep 1980 | RED |
| 136 | Field Rigging Check - PN 369A8013 Series and PN 369A8051 Series Heater Control Valve Assembly | 16 Feb 1979 | RED |
| 139 | Inspection and Repair - Tail Control Station 142.00 Bellcrank Support, PN 369A3035-11 and 369A3035-15 | 11 Jun 1979 | RED |
| 140 | Inspection of Main Rotor Blade Root Fitting Assemblies, Inspection of Main Rotor Hub Lead-Lag Assemblies | 05 Sep 1979 | RED |
| 144 | Kit Installation, PN 369D290140 - Auxiliary Fairing and Seals Air Filter (Particle Separator) | 23 Jul 1979 | RED |
| 146 | Inspection - Collective Torque Tube Support Bracket (PN 369A7304 Magnesium, PN 369H2608 Aluminum) and Collective Bungee Support Bracket (PN 369A7339 Magnesium, PN 369N2650 Aluminum) | 01 Aug 1979 | RED |
| 150 | PN 369A1800 Series and PN 369H1800 Tail Rotor Pitch Control Assembly - Seating of Bearing Inner Race; Torque Increase for PN 369A1817 Locknut | 26 Nov 1979 | RED |
| 152 | Removal of Filter Gasket - Engine Air Inlet (Particle Separator) Filter Kit Installation PN 369H90148 and 369H90148-501 | 03 Mar 1980 | RED |
| 155 | Polarity Check of Diode Assemblies | 30 Jun 1980 | RED |
| 156 | Identification and Possible Rework of Seat Belt and Shoulder Harness Assemblies | 11 Jul 1980 | RED |
| 158 | Wiring Modification - Utility Light Circuit and Transmission Oil Pressure and Temperature Warning Light Circuit | 30 Sep 1980 | RED |
| 162.1 | Inspection of PN 369A7003-3 Swashplate Bearing | 14 Sep 1981 | RED |
| 163 | Sealing of Interface of Abrasion Strip and Main Rotor Blade Skin | 30 Jan 1981 | RED |
| 164.1 | Inspection of Overrunning Clutch Sprag Assembly | 10 May 1983 | RED |
| 165 | Field Inspection and Repair of Tail Rotor Transmission Main Housing Assembly PN 369A5401 | 15 Apr 1981 | RED |
| 167 | Shimming Procedure for Gas Producer Interconnecting Torque Tube Assembly | 04 May 1981 | RED |
| 168 | Special Inspection of PN 369A7003-1 Swashplate Bearing Assembly | 06 May 1981 | RED |
| 169 | Replacement of PN 369A7706-3 RPM Governor Lever Control Rod (Ref. FAA AD 82-01-08) | 15 May 1981 | RED |
| 170 | Corrosion Inspection/Treatment One-Way Lock Support Assembly PN 369A7314 and 369N2648 | 04 Jun 1981 | RED |
| 171 | Inspection/Modification of Breeze Corporation Inc. Hoist PN BI-16600-12 | 18 Jun 1981 | RED |

Current indexes are available at: www.mdhelicopters.com

SERVICE BULLETINS (CONT.)

| 369H SB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|--|----------------|--------|
| 172 | Inspection and Torque Requirements for Scroll Mounted Bleed Air Fittings | 21 Jul 1981 | RED |
| 173 | Deactivation of Main Rotor Brake System (if installed); Periodic Inspection of Tail Rotor Drive Shaft Forward Flexible Coupling PN 369A5501 or 369H92564. Installation of Fail Safe Device at Tail Rotor Drive Shaft Forward Flexible Coupling PN 369A5501 or 369H92564 Check of Flexible Couplings. | 02 Nov 1981 | RED |
| 174 | Main Rotor Brake System PN 369H90123 Series - Installation of Master Cylinder stop PN 369D292585 | 28 Aug 1981 | RED |
| 175 | Inspection of PN 369A1200 Series Main Rotor Hub Assembly; Inspection of PN 369A1220 Main Rotor Blade Lead-Lag Pivot Bolt (Vertical Hinge Pin) | 04 Jan 1982 | RED |
| 177 | Instrument Cluster 3-Pack Conversion - AC to Rochester | 15 Feb 1982 | RED |
| 179 | Replacement of Intercom (ICS) Switch and Jack Assembly | 01 Jul 1982 | RED |
| 181 | New Shimming Procedure for Tail Rotor Drive Shaft Forward Flexible Coupling PN 369A5501 or 369H92564, With Fail Safe Device Installed | 12 Oct 1982 | RED |
| 182 | Replacement of Float Inflation System Solenoid Valves With Squib Valves PN 369H90121 Series Emergency Float Assemblies | 10 Jan 1983 | RED |
| 183 | Relocation of Engine Air Inlet Filter Bypass Door Aft Pulley PN 369A8448 and Bracket PN 369A8447, and Particle Separator Filter PN 369H90152-3 Gasket Inspection | 10 Jan 1983 | RED |
| 184 | Center Passenger Seat, Lap Belt Check; Preflight Check of Passenger Lap Belt and Shoulder Strap Fit and Adjustment | 15 Feb 1983 | RED |
| 185 | Fuel System Service, Maintenance and Testing | 15 Mar 1983 | RED |
| 186 | Fuel Vent System Hose Inspection | 02 May 1983 | RED |
| 187.1 | Installation of Collective Stick Support Bracket Reinforcement Strap | 23 Nov 1983 | RED |
| 189.1 | Inspection and Overhaul of Fuel Shutoff Valve (PN 369A8104-5) | 20 Aug 1984 | RED |
| 190 | Battery Case Inspection | 28 Oct 1983 | RED |
| 191 | Main Rotor Swashplate Bearing Inspection and Possible Replacement (Ref. FAA AD 84-01-02R1) | 23 Dec 1983 | RED |
| 192 | Instrument Cluster 4-Pack Conversion AC to Rochester | 15 Feb 1984 | RED |
| 193 | Fuel Shut-Off Valve Control Cable PN 369A8137-503 and -603 Pull Test | 10 Apr 1984 | RED |
| 195 | Riveting Tip Cap to Tail Rotor Blade (Ref. FAA AD 86-01-04) | 27 Aug 1984 | RED |
| 196 | Inspection - Landing Gear Feet and Strut | 01 Oct 1984 | RED |
| 197.2 | One-Time Inspection of Tail Rotor Blade Leading Edge Abrasion Strip Bonding Pilot's Preflight Check of Tail Rotor Blade Leading Edge Abrasion Strip (Ref. FAA AD 94-18-08) | 23 Mar 1987 | RED |
| 198.1 | Corrosion Removal - Main Rotor Drive Shaft ID | 30 Oct 1987 | RED |
| 199.1 | Riveting Tail Rotor Tip Cap to Blade (Ref. FAA AD 86-01-04) | 01 May 1985 | RED |
| 200 | Non - Airworthy Parts | 18 Mar 1985 | RED |
| 201 | Exit Warning Decal (Including AC 91-32 Safety In and Around Helicopters) | 07 Aug 1985 | RED |
| 202 | EON Seat Belt Removal | 15 May 1986 | RED |
| 205 | United Instrument Inc. Altimeter - Inspection/Rework | 20 May 1986 | RED |
| 206.1 | Tail Rotor Driveshaft Aft Fail Safe Device - Installation/inspection (Ref. FAA AD 86-20-07) | 28 Nov 1986 | RED |
| 208.1 | Daily Pre-flight Examination of Main Rotor Blade Leading Edge Abrasion Strip Bonding | 10 Sep 1992 | RED |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
 4555 East McDowell Road
 Mesa, Arizona 85215-9734

SERVICE BULLETINS (CONT.)

| 369H SB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|--|----------------|--------|
| 209 | 3659A8010 Engine Oil Pressure and Torque Tube Pull Test | 15 Sep 1987 | RED |
| 210 | Start Pump Wire Routing and Fuel Quantity Sender Inspection | 15 Sep 1987 | RED |
| 211.6 | Inspection of Main Rotor Blade Root Fitting Assemblies - Inspection of Main Rotor Hub Lead-Lag Link Assemblies (Ref. FAA AD 95-03-13) | 03 Jan 2000 | RED |
| 212.2 | Inspection and Replacement of Tail Rotor Fork Bolt (369A1602) | 21 Apr 1989 | RED |
| 213 | Replacement of 369A8442-Basic Latch Assembly on the Particle Separator Door | 18 Dec 1987 | RED |
| 214 | Main Rotor Hub Strap Pack Lamination Inspection and Tri-Flow Wash Procedure (Ref. FAA AD 89-02-01R1) | 15 Jan 1988 | RED |
| 215.2 | Inspection of 369A5352 Outer Race of Overrunning Clutch Assembly PN 369A5350 (Ref. FAA AD 98-09-02) | 11 Apr 1997 | RED |
| 216 | One-Time Inspection of the Transmission Driveshaft Couplings - 369H5660 (Ref. FAA AD 90-01-08) | 05 Apr 1989 | RED |
| 217.1 | One-Time Inspection and Rework of Main and Tail Rotor Control Tubes (PN's 369A7007, 369A7009, 369A7011, and 369A7012) (Ref. FAA AD 89-23-14) | 21 Jul 1989 | RED |
| 218 | One-Time Inspection of Aeroquip Hoses (PN's 369A8352, 369H8306, 369H8025, 369H8024-5 and 369D28651) | 12 Jun 1989 | RED |
| 219 | Finite Service Life Reduction of the Tail Rotor Tension Torsion Strap Pack Assembly PN 369A1706 (Basic) (Ref. FAA AD 89-11-05) | 20 Jun 1989 | RED |
| 220 | One-Time Inspection of 369A5358 Lockwasher in the Overrunning Clutch Assembly and Inspection of Engine Output Drive Splines | 27 Oct 1989 | RED |
| 221 | Installation of Oil Flow Restricting Devices into the Engine Oil and Torque Pressure Sensing System | 27 Oct 1989 | RED |
| 222 | Conversion to 369A5350-41 Overrunning Clutch Sub-Assemblies | 04 May 1990 | RED |
| 223 | One-Time Replacement of Polycarbonate Cover Assemblies (369A9817) | 15 Jun 1990 | RED |
| 224 | One-Time Replacement to Tail Rotor Blade Pitch Arm Bolt Attaching Nuts | 15 Jun 1990 | RED |
| 225.1 | One-Time Torque Check and Inspection of Main Rotor Blades | 15 May 1991 | RED |
| 226.1 | One-Time Installation of 369D24054-3 Warning Decals in the Engine Compartment | 04 Sep 1990 | RED |
| 227R1 | Inspection of Lead-Lag Link Attach Nuts | 06 Jul 2009 | RED |
| 228 | One-Time Inspection of 369H8407 Engine Bleed Air Tube Flexible Area | 21 Nov 1990 | RED |
| 229 | One-Time Reinstallation of 369A1602 Tail Rotor Fork Bolt | 21 Nov 1990 | RED |
| 230.1 | Pre-flight Check and One-Time Inspection of tail Rotor Blades (Ref. FAA AD 91-08-02) | 01 Mar 1991 | RED |
| 231 | One-Time Rework of Main Transmission Oil Cooling Fan Mounting Bracket | 01 Feb 1991 | RED |
| 232 | One-Time Addition of Rivets to Tail Rotor Abrasion Strip (Ref. FAA AD 94-18-08) | 27 Sep 1991 | RED |
| 233 | Inspection of Overrunning Clutch Outer Race - 3695352 Overrunning Clutch Assy. | 17 Jan 1992 | RED |
| 234.1 | Inspection/Rework of Fuel Vent System (Helicopters Equipped With 369H8108, 369H8108-501 or 369H8108-503 Fuel Vent Line Emergency Shutoff Valve) (Ref. FAA AD 93-18-05) | 10 Sep 1992 | RED |
| 235 | One-time Inspection/Rework of Engine Air Inlet Area | 20 Mar 1992 | RED |
| 236 | Four-Way Trim Switch Replacement | 10 Mar 1994 | RED |
| 237 | Firewall Fuel Fitting Modification | 26 Sep 1994 | RED |

Current indexes are available at: www.mdhelicopters.com

MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734



SERVICE BULLETINS (CONT.)

| 369H SB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|--|----------------|--------|
| 238 | Tail Rotor Blade Abrasion Strip Modification (Ref. FAA AD 95-03-11) | 26 Oct 1994 | RED |
| 239 | Main Rotor Blade Root End Inspection (Ref. FAA AD 96-10-09, 98-15-26) | 27 Oct 1995 | RED |
| 240 | Input Shaft Coupling Assembly Inspection (Ref. FAA AD 99-04-12) | 26 Sep 1997 | RED |
| 241R1 | T/R Blade, Leading Edge Inspection for Cracks | 03 May 1999 | RED |
| 243R3 | M/R Blade Root End Inspection and Termination Action for Suspect M/R Blades (Ref. FAA AD 98-15-26) | 13 Jul 1998 | RED |
| 244 | Landing Gear Strut Inspection and Fairing Modification | 07 Apr 2000 | RED |
| 245R2 | Main Rotor Blade Assembly Torque Event Inspection (Ref. FAA AD 2005-21-02) | 04 Feb 2004 | RED |
| 246R1 | Tail Rotor Blade Abrasion Strip Tap Test and Modification | 23 Jan 2006 | RED |
| 247 | Tail Rotor Blade Assembly, One Time Inspection | 26 Apr 2007 | RED |
| 248R1 | Oil Cooler Belt, One Time Inspection | 13 Mar 2009 | RED |
| 249 | Not Issued | | |
| 250 | Kamatics Shaft and Coupling Overhaul Program | 22 Dec 2010 | RED |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

MODEL 369H (500C) HELICOPTER TECHNICAL BULLETIN INDEX

Technical Bulletins are service information notices which are not mandatory (formerly blue border), and require the performance of maintenance and/or alteration for compliance.

NOTE

As Service Information Notices are re-issued, they will be identified as Bulletins using the helicopter model designation as the prefix.

TECHNICAL BULLETINS

| 369H TB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|---|----------------|--------|
| 17 | Installation – Dual Bolt, Lower Vertical Stabilizer | 21 Apr 1970 | BLUE |
| 30 | Modification Kit PN 50023 – Heat Control Valve Assembly | 21 Dec 1970 | BLUE |
| 35 | Modification Kit PN M50436 – Engine-Out Warning Horn Support | 18 May 1971 | BLUE |
| 39 | Provision for Drainage of Water Entrapment Areas | 23 Aug 1971 | BLUE |
| 42 | Shock-Mounted Vertical-to-Horizontal Stabilizer Strut Assembly | 17 Dec 1971 | BLUE |
| 49 | Relocation of Engine Fuel Supply Hose | 01 May 1972 | BLUE |
| 51 | Rework – PN 369H2048 Door Latching System (Autolatching) | 24 Jul 1972 | BLUE |
| 55 | Valve Housing Modification – Heat Control Valve Assembly, Cabin Heating System Kit Installation | 01 Mar 1973 | BLUE |
| 57 | Engine Anti-Icing and Cabin Heating System Installations – Conversion from Electrical to Manual Operation | 01 May 1973 | BLUE |
| 58 | Installation of SCR Assembly – Auto-Re-ignition Modification Kit PN M50036 | 29 May 1973 | BLUE |
| 64 | Sealing Skid Mounted Position Lights PN 369H4534-21 and -22 | 03 Mar 1974 | BLUE |
| 67 | Corrosion Prevention/Inspection – Main Rotor Blade PN 369A1100-501 | 15 Apr 1974 | BLUE |
| 69 | Installation of Heater System Muffler Assembly | 10 Jun 1974 | BLUE |
| 70 | Installation – Fuel Shutoff Valve Control PN 369A8136-503 or -701 | 05 Aug 1974 | BLUE |
| 71 | Noise Filter Installation – Modification Kit PN M50039 | 05 Aug 1974 | BLUE |
| 72 | Emergency Release Mechanism Modification (M50041), Cargo Hook Kit Installation (369H90065) | 05 Aug 1974 | BLUE |
| 77 | Relocation – Magnetic Compass PN 369H4508 | 30 Sep 1974 | BLUE |
| 80 | Bendix Service Bulletin No. 109, Dated 10-22-74 Inspection, Flexible Coupling Locknut | 18 Nov 1974 | BLUE |
| 81 | Modification – Fuel Cell Vent System Installation (Modification Kit PN M50042) | 02 Jan 1975 | BLUE |
| 84 | Inspection – Hinges PN 369A8437; Engine Air Filter Bypass Door | 05 May 1975 | BLUE |
| 85.1 | Relocation – Fuel Filter Pressure Switch PN 369H8144 | 20 Jun 1975 | BLUE |
| 89 | Modification – Tank Unit Fuel Quantity Rheostat PN 369A4225-501 (Kit PN M50047) | 07 Nov 1975 | BLUE |
| 90 | Field Modification – Door Latch Kit PN M50440 | 11 Dec 1975 | BLUE |
| 92 | Field Maintenance – Main Rotor Damper Assembly PN 369A1400-603 to -605 Configuration | 01 Mar 1976 | BLUE |
| 93 | Operational Check and Adjustment of Autolatching Mechanism – Pilot and Cargo Doors | 11 Mar 1976 | BLUE |
| 94 | Removal of Inboard Tab – Main Rotor Blade PN 369A1100-501 | 01 Apr 1976 | BLUE |

Current indexes are available at: www.mdhelicopters.com

MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734



TECHNICAL BULLETINS (CONT.)

| 369H TB369H- OR HN- | SUBJECT | Date ISSUED | BORDER |
|---------------------------|--|----------------|--------|
| 104 | Modification Kit PN M50455 – Fan Assembly, Engine Oil and Compartment Cooling | 05 Nov 1976 | BLUE |
| 112 | Field Fix for Main Rotor Swashplate Uniball | 24 Dec 1976 | BLUE |
| 113 | Tachometer Generator Assembly – Modification Kit PN M50049 | 24 Dec 1976 | BLUE |
| 119 | Door Latch Synchronization Check – Pilot's and Cargo Doors, Autolatching Mechanisms | 12 Sep 1977 | BLUE |
| 120 | Installation of Auxiliary Drain Valve, Fuel System Installation PN 369H92255 Drain Kit | 03 Oct 1977 | BLUE |
| 122 | Removal of Capacitor – Voltage Regulator, AAE or LSI Model VR204 Installation of Varistor – Landing Light Relay PN 369A4558 or MS24166D1 | 06 Feb 1978 | BLUE |
| 123 | Installation – Tail Rotor Pitch Control Links PN 369A1907-5 | 03 Apr 1978 | BLUE |
| 125 | Replacement of Plenum Wall Fittings – Torque Pressure Gage Tubing and Engine Oil Pressure Gage Tubing | 06 Jun 1978 | BLUE |
| 127 | Field Inspection and Corrosion Repair – Main Rotor Drive Shaft PN 369A5500 | 05 Jul 1978 | BLUE |
| 129.1 | Installation of Anti-Ice Fuel Filter PN 369H90022-501 | 24 Nov 1980 | BLUE |
| 132 | Field Repair – Cyclic Trim Actuator Assemblies PN 369A7170 and 369A7171 Series | 29 Jan 1979 | BLUE |
| 135 | Field Repair – Trim Tab, Main Rotor Blade PN 369A1100 Series | 16 Apr 1979 | BLUE |
| 137 | Replacement of Radio Transmit/Intercom Trigger Switch; – Rework of Cycle Stick Grip Assembly | 10 May 1979 | BLUE |
| 141.1 | Installation of Voltage Transient Suppressors | 26 Nov 1979 | BLUE |
| 143 | Rework of Ground Handling Wheel Assemblies (Float Type) | 20 Aug 1979 | BLUE |
| 151 | Installation of Cabin Heat Duct (Fiberglass) Assemblies PN 369D22099-101 | 15 Jan 1980 | BLUE |
| 154 | Rework of One-Way Lock Assembly PN 369A7010 Series | 02 Jun 1980 | BLUE |
| 157 | Conversion from Pressure Switch Activated to EPO Activated Auto-re-ignition System | 01 Aug 1980 | BLUE |
| 159 | Drain Kit Installation PN 369D28300-501 Engine Oil Tank and Oil Cooler | 18 Aug 1980 | BLUE |
| 160 | Relocation of Auto-Re-ignition Controls and Modification of System for Full Time Operation (FAA AD 80-24-04) | 22 Feb 1983 | BLUE |
| 161 | Rework of Static Pressure Tube Installation to Minimize Altimeter Needle Oscillation | 08 Dec 1980 | BLUE |
| 166 | Installation of Engine Air Inlet Deflector Kit PN M30287-501 | 21 Apr 1981 | BLUE |
| 176 | Installation of PN 3569H4237-21 Resistor Board Assembly for Easier Accurate Adjustment of TOT Indicator | 01 Feb 1982 | BLUE |
| 178 | Rework of PN 369A9905-Basic and -3 Ground Handling Wheel Assemblies to Accommodate Installation of New PN 369D26107 Landing Gear Skid Fittings | 29 Jun 1982 | BLUE |
| 188 | Installation and Replacement of Protective sleeve (Speedi-Sleeve PN 084956) on Tail Rotor Transmission Output Gearshaft | 21 May 1983 | BLUE |
| 203 | Installation of Oil Tank Filler Nozzle Strainer Assembly PN 369D28318 | 15 Apr 1986 | BLUE |
| TB369H-002 | Cyclic Grip Modification | 02 Jun 1999 | N/A |
| TB369H-003 | Cyclic Trim Actuator Housing Replacement or Modification | 12 Jun 2001 | N/A |
| TB369H-004 | Engine Automatic Re-ignition Modification | 13 Mar 2009 | N/A |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

MODEL 369H (500C) HELICOPTER SERVICE LETTER INDEX

NOTE

As Service Information Letters are re-issued, they will be identified as Service Letters using the helicopter model designation as the prefix.

Service Letters are are not mandatory and do not provide maintenance instructions.

| 369H SL369H- OR HL- | SUBJECT | Date |
|------------------------------------|---|-------------|
| 3.1 | Bendix Avionics Equipment Repair and Service | 05 Nov1973 |
| 6.1 | Special Wrenches for Field Replacement of Main Rotor Pitch Bearing Studs | 03 May 1971 |
| 11 | Tail Rotor Swash – Cold Weather Operation | 12 Oct 1971 |
| 14 | Inspection of Nickel-Cadmium Batteries – FAA Airworthiness Directive Note 72-21-5 | 17 Dec 1971 |
| 15 | Breeze BL-16600-11 Hoist Winch Assembly | 10 Jan 1972 |
| 16 | Allison Model 250 Engine – Sales and Service | 07 Feb 1972 |
| 17 | Approved Fuel for Allison Model 250 Series Engine | 14 Feb 1972 |
| 18 | New Cargo Hook Plate | 01 May 1972 |
| 19 | Identification Plates – PN 369A5351 Overrunning Clutch Housing and PN 369A54350-11 Overrunning Clutch Sub-assembly | 22 May 1972 |
| 21.2 | Installation of Surplus Military Parts or Salvaged Used Parts on Model 500 Helicopters | 10 Feb 1984 |
| 26.1 | Special Tools for Installation of Tail Rotor Control Rod Grommets PN WSI-B-12AS | 22 Jun 1973 |
| 30 | Replacement of Boom Fairing Assemble on First Production Helicopter, SN 0001 thru 0100 | 12 Jul 1973 |
| 31 | Ordering Information – Pilot's Door Assembly PN 369A2002 or 369H2025; Passenger Door Assembly PN 369H2032 or 369H2038 | 12 Jul 1973 |
| 32.1 | Metal Tail Rotor Blades – Replacement for Fiberglass Tail Rotor Blade | 05 Nov 1976 |
| 34 | Discussion of Hughes Serial Numbering Method | 31 May 1974 |
| 36 | Inflatable Floats – Service, Maintenance and Repair Facilities | 05 Aug 1974 |
| 37 | Extreme Turbine Outlet Temperature Effects on Turbines | 28 Aug 1974 |
| 38 | Modification Kit Availably – Torquemeter Bleed Valve PN M50043 and Static Pressure Tube Bleed Valve PN M50439 | 05 May 1975 |
| 39.3 | Main Transmission PN 369A5100-709 Upgraded Transmission – Factory Availability for Overhaul | 26 Jul 1976 |
| 40 | Interchangeability of tabbed Main Rotor Blades (PN 369A1100-501) With Untabbed Main Rotor Blades (PN 369A1100-501) | 21 Jul 1975 |
| 42 | Recharging of Inflation Bottles for Emergency Floats | 07 Nov 1975 |
| 44 | Allison Model 250-C20 Series Engine – Installation of New High Pressure Fuel Filter Assembly | 10 Aug 1976 |
| 46 | Periodic Inspection of Particle Separator Kit Installation; Removal of Outlet Screen During Cold Weather | 24 Dec 1974 |
| 47 | Improved Engine Air Filter Assembly for Particle Separator Filter Kit | 24 Dec 1976 |
| 53 | Replacement of PN 369A1613-3 – Metal Tail Rotor Blade Assemblies | 22 Jul 1977 |
| 55 | Unitization of Engine Air Particle Separator and Engine Compressor Water Wash Kits | 14 Feb 1978 |
| 58 | (INSCO) Instrument Specialties Co. Inc., Authorized Repair Stations and Official Sales and Service Facilities | 22 May 1978 |

Current indexes are available at: www.mdhelicopters.com

MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734



| 369H SL369H- OR HL- | SUBJECT | Date |
|------------------------------------|---|-------------|
| 61 | Particle Separator Installation and Inspection and Possible Removal of Circular Filter Screens | 08 Sep 1978 |
| 64 | Operation and Maintenance Guidelines for Model 250 Series Engine Fuel System | 01 Aug 1979 |
| 67 | New Seal Requirement for Overhaul of PN 369D23600 and 369D23601 Landing Gear Damper Assemblies | 26 May 1980 |
| 70 | Compliance With FAA Airworthiness Directive and Hughes Mandatory (RED) Border Service Information Notices | 30 Sep 1980 |
| 72 | Substitution of Wet Spline Drive Starter-Generator for Existing Dry Spline Drive Starter-Generator | 13 Mar 1981 |
| 75 | Tail Rotor Driveshaft Flexible Coupling PN 369A5501 and 369H92564 Treatment With Molykote Metal Protector | 21 Aug 1981 |
| 76 | New Protective Boots for Main Rotor Hub and Tail Rotor Assemblies | 01 Sep 1981 |
| 78 | Field Replacement of 'O' Ring for PN 369A8321 Oil Tank Filler Cap | 02 Nov 1981 |
| 80 | New PN 369D28237 Cushion for Tailpipe Hanger Assembly Designed for Longer Wear | 01 Feb 1982 |
| 84 | Ground Testing - Engine Automatic Re-ignition and Engine Anti-Ice Fuel Filter System | 22 Nov 1982 |
| 85 | Prevention of Water Leakage Through Canopy Geon Strips | 10 Jan 1983 |
| 86 | Handling and Shipping Gyros | 01 Feb 1983 |
| 87 | New Attitude Gyro and Support Assembly | 25 Feb 1983 |
| 88 | Surplus or Bogus 369D21100 Series Main Rotor Blades | 10 Feb 1984 |
| 89 | Unauthorized Tail Rotor Teeter Bearings | 16 May 1984 |
| 91 | Major Installations and Alterations to Your Hughes Helicopter | 12 Nov 1984 |
| 93 | Explanation of MDHC Parts Serialization | 15 Sep 1985 |
| 94 | Main Rotor Hub Overhaul Authorization | 17 Mar 1986 |
| 97 | Re-lubrication of Bearings in Storage | 06 Apr 1987 |
| 98 | External Scavenge Oil Filter System | 01 May 1987 |
| 99 | Unauthorized Distribution of Main Rotor Hub Overhaul Manual | 15 Jun 1987 |
| 100 | Illustrated Parts Breakdown of Ground Handling Wheel Assemblies (PN 369D26 10) | 19 Feb 1988 |
| 102 | Addition of Identification Decal on Aircraft Exterior (Compliance to FAR 45.11 [D]) | 06 May 1988 |
| 104 | Additional Inspection Requirements of the Breeze-Eastern Rescue Hoist System | 18 May 1988 |
| 105 | Chafe Wrapping of Stainless Steel Tube Assemblies and Allison Commercial Service Letter CSL 145, CSL 1140 and CSL 3092, Dated May 1, 1988 | 26 May 1988 |
| 108.2 | Facet Scavenge Oil Filter Kit, PN 1741050 (369H Series, 369D and 369E) and PN 1741300 (369F/FF) | 21 Nov 1990 |
| 110 | Validity of Spectrum Oil Analysis Program (S.O.A.P.) | 15 Jan 1989 |
| 113R3 | Customer Request for Original Aircraft Records | 10 Nov 2004 |
| 116 | Availability of Wire Strike Protection System (Trademark WSPS) on all MDHC 369 Series Helicopters | 15 Sep 1989 |
| 119 | Compliance to (Breeze-Eastern) Customer Service Bulletin CSB-120 (Warning Plate for Cargo Hooks) | 15 Dec 1989 |
| 120 | Availability of Skid Mounted Light Assembly Shims | 01 May 1991 |
| 121 | Observation of Main Rotor Hub Hoisting Eye Bolts | 27 Sep 1991 |
| 122 | Main Rotor Hub Balancing | 11 Oct 1991 |
| 124R3 | Surplus OH-6A Helicopter Issues | 10 Nov 2004 |
| 125 | Main Rotor Blade Inspection Program | 27 Jan 1993 |

Current indexes are available at: www.mdhelicopters.com



369H PUBLICATION INDEXES
MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

CSP-369H-INDEX

| 369H SL369H- OR HL- | SUBJECT | Date |
|------------------------------------|--|-------------|
| 126 | Antenna Location and Flight Maneuver Caution | 22 Mar 1993 |
| 128 | Compensation for Complying With Tail Rotor Blade Abrasion Strip Notice | 10 May 1995 |
| 129 | Increased Time Between Overhaul Period on OH-6A Main Rotor Hubs and 369A5400-700 Tail Rotor Transmission Utilization | 25 Aug 1995 |
| 131 | Service Letter/Notice/Bulletin Designation | 13 Feb 1998 |
| 132R1 | MD Helicopters Model 369/500N/600N Torque Event/Retirement Index Number Explanation | 15 May 2001 |
| 133 | Transfer of Ownership of the Light Helicopter Line | 19 Feb 1999 |
| 134 | Required Inspections and Critical Inspection Areas | 16 Aug 1999 |
| 135 | Availability of Federal Aviation Administration Airworthiness Directives Affecting MD Helicopters | 23 May 2000 |
| 136R1 | Availability of Federal Aviation Administration Supplemental Type Certificates for MD Helicopters | 26 Jun 2000 |
| 137 | New Standard Warranty Statement | 02 Mar 2001 |
| 138 | Repair and Overhaul of 4-Bladed Main Rotor Hubs | 26 Feb 2002 |
| 139 | Availability of MDHI Publications in Electronic Format | 17 Sep 2003 |
| 140 | Helicopter Operation in Volcanic Ash Atmosphere | 06 May 2010 |
| 142 | Kamatics Shaft and Coupling Overhaul/Exchange Program Announcement | 22 Dec 2010 |
| 143 | Technical Publications Price Increase | 22 Dec 2010 |

Current indexes are available at: www.mdhelicopters.com



This page intentionally left blank!



MODEL 369H (500C) HELICOPTER CANCELED PUBLICATIONS LIST

1. Canceled Maintenance Manuals

- (1). The following is a list of Maintenance Manuals that have been canceled.
- (2). If the Technical Manual is superseded by another Technical Manual, it will be noted in the Publication Title column in parenthesis after the title.

| Publication Number | Publication Title |
|--------------------|--|
| CSP-H-2A | Configuration Supplement HE/HS (Superseded by CSP-H-2) |
| CSP-369ARFM-1 | Flight Manual / Owners Manual, Hughes Model 369A (OH-6A) Helicopter, Issued 30 April 1969, Last Revised 16 June 1975 (Obsoleted) |

2. Canceled or Superseded Service Bulletins/Service Information Notices

- (1). The following is a list of Bulletins/Notices that have been canceled or superseded.
- (2). Updated information, pertinent to the Bulletin/Notice, has been incorporated into the appropriate manuals.
- (3). If the Bulletin/Notice is superseded by another Bulletin/Notice, it will be noted in the Subject column in parenthesis after the description.

| 369H SB369H- OR HN- | SUBJECT | Date CANCELED |
|---------------------------|--|-------------------------|
| 2 | Inspection – Controls Tunnel Lockbolts | Prior to 15 Jul 1974 |
| 3.1 | Inspection – Belt–Driven Oil Cooler Installation (Superseded by HN–27) | Prior to 15 Jul 1974 |
| 4 | Inspection – NAS1291–4 Nuts | Prior to 15 Jul 1974 |
| 5 | Inspection – Microphone Filter P/N 369H92515 | Prior to 15 Jul 1974 |
| 6 | Fuel Cell Access Doors – Hardware Installation | Prior to 15 Jul 1974 |
| 7 | Inspection and Rework – Dual Controls Installation, Copilot Collective Stick Interference | Prior to 15 Jul 1974 |
| 9 | Inspection and Adjustment – Engine Controls | Prior to 15 Jul 1974 |
| 10.1 | Inspection and Removal – Landing Gear Oleo Dampers, P/N 369A6300–501 and 369A6300–503 | Prior to 15 Jul 1974 |
| 12 | Inspection – Crew Assist Handle, P/N 369H6571–211 | Prior to 15 Jul 1974 |
| 13 | Modification Kit No. M50014 – Engine Cooling Installation, Transmission Cover Connecting Ducts | Prior to 15 Jul 1974 |
| 14 | Kit Installation (M30327) – Belt Driven Oil Cooler Blower Assembly (Superseded by HN–27) | Prior to 15 Jul 1974 |
| 16 | Rework – Hinge, Filter Bypass Door (369A8437) | Prior to 15 Jul 1974 |
| 19.1 | Inspection – Tail Rotor Blades for Separation of Abrasion Strip | Prior to 15 Jul 1974 |
| 20 | Special Instructions – Belt Driven Oil Cooler Blower System (Superseded by HN–27) | Prior to 15 Jul 1974 |
| 21.1 | Replacement – Main Rotor Pitch Control Bearing Housing Assembly, P/N 369A1304–3 | Prior to 15 Jul 1974 |
| 22 | Cigar Lighter – Installation Modification (M50016) | Prior to 15 Jul 1974 |
| 24.1 | Inspection and Rework – Overrunning Clutch (P/N 369A5350 and 369A5350–601) | Prior to 15 Jul 1974 |
| 25 | Modification – Gas Producer Control, P/N M30240 | Prior to 15 Jul 1974 |
| 27.1 | Kit Installation (M50024) – Modification, Transmission and Coupling Fan Assembly | Prior to 15 Jul 1974 |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
 4555 East McDowell Road
 Mesa, Arizona 85215-9734

| 369H SB369H- OR HN- | SUBJECT | Date CANCELED |
|---------------------------|--|-------------------------|
| 31 | Installation of Cotter Pins – 369H2080 Aft Fairing Access Door | Prior to 15 Jul 1974 |
| 32 | Cable Return Spring Installation – P/N 369H90065 Series Cargo Hook Installations | Prior to 15 Jul 1974 |
| 33 | Replacement – Bearings, Oil Cooler Blower Shaft | Prior to 15 Jul 1974 |
| 44 | Replacement of Tail Rotor Blades, P/N 369A1710 Series | Prior to 15 Jul 1974 |
| 59 | Modification – Hoist Winch Assembly, PN 369H92563 or 369H92015 (Breeze BL-16600-11 and -20 Series Hoists) | 01 Nov 1983 |
| 105 | Preliminary or “Rough” Adjustment of Tail Rotor Balance (With Chadwick-Helmuth Vibrex Balance System) | 01 Nov 1983 |
| 106 | Periodic Inspections – Landing Gear Damper Assemblies, PN 369H6340 and 369H92131 | 01 Nov 1983 |
| 115 | Field Replacement – Engine Fuel Filter Pressure Switch Assembly | 01 Nov 1983 |
| 126 | Un-Assigned | |
| 133.2 | Operational Check – Engine Fuel Pump Filter Pressure (By-Pass) Switch Assembly | 01 Nov 1983 |
| 134 | PN 369H7825 Droop Control Bellcrank Assembly (Station 68.0) – Relocation of Locknut and Installation of Spacer | 01 Nov 1983 |
| 145.2 | 100 Hour Periodic Inspection Fuel Tank Sending Unit and Fuel Low Warning Light Indication System | 17 Sep 2003 |
| 149 | Installation of Chafing Bar Assemblies – PN 369H90070 Hoist Kit Installation | 01 Nov 1983 |
| 153 | Main Rotor Transmission Cover Assembly – PN 369H8063-505 – Retention of Cover Seals, PN 369H8063-85, -89 and -91 | 01 Nov 1983 |
| 180 | Preflight Check of Tail Rotor Blade Leading Edge Abrasion Strip | 01 Sep 1985 |
| 194 | Oil Pressure and Torque Pressure Fire-Wall Fitting Check (Superceded by HN-209) | 15 Sep 1987 |
| 204 | Main Rotor Hub Strap Pack Inspection (Superceded by HN-214) | 15 Jan 1988 |
| 207 | Tail Rotor Elastomeric Bearing Shimming Procedure | 22 Feb 2000 |
| 242 | M/R Blade Root End Inspection (Superceded by HN-243R3) | 13 Jul 1998 |

Current indexes are available at: www.mdhelicopters.com

3. Canceled or Superseded Technical Bulletins/Service Information Notices

- (1). The following is a list of Bulletins/Notices that have been canceled or superseded.
- (2). Updated information, pertinent to the Bulletin/Notice, has been incorporated into the appropriate manuals.
- (3). If the Bulletin/Notice is superseded by another Bulletin/Notice, it will be noted in the Subject column in parenthesis after the description.

| 369H TB369H- OR HN- | SUBJECT | Date CANCELED |
|------------------------------------|--|--------------------------|
| 001R1 | Door Seal Replacement | 15 Mar 2002 |
| 15 | Corrosion Protection – Ni-Cad Battery Receptacle Conductor Leads | Prior to 15 Jul 1974 |
| 26.1 | Installation – Winterization Kit P/N 369H90127 | Prior to 15 Jul 1974 |
| 29 | Modification Kit (M30239) Improved Door Sealing | Prior to 15 Jul 1974 |
| 36 | Modification Kit (M50030) – De-Icer Actuator | Prior to 15 Jul 1974 |
| 41 | New Latching System – Aft Fairing Access Door, P/N 369H2080 | Prior to 15 Jul 1974 |
| 43.1 | New Engine Air Inlet Screen Assembly | Prior to 15 Jul 1974 |
| 46 | Shim Installation – Tail Rotor Hub at Fork (Teeter) Bearings; Replacement – Tail Rotor Fork Bearings | Prior to 15 Jul 1974 |
| 52.1 | Engine Conversion Kit – Allison Model 250-C20 Series Engine | 01 Nov 1983 |
| 60 | Modification – N1/NR Disable Switch Installation | 01 Nov 1983 |
| 63.1 | Wiring Modification – 369H4514-3 Engine-Out Warning Unit and King or RCA VHF Transceiver | 01 Nov 1983 |
| 76 | Vibration Damper Kit No. M50045 – Landing Gear Skid Assembly | 01 Nov 1983 |
| 78 | Hinge Pins – Tail Rotor Pedal Heel Strips | 01 Nov 1983 |
| 100 | Installation – Battery Compartment Ventilation Scoop | 01 Nov 1983 |
| 107.1 | Installation – Engine Compressor Water Wash Kit, PN 369H92537 | 01 Nov 1983 |
| 138 | Installation of Protective Screen – Static Pressure Tube, Aft End | 01 Nov 1983 |
| 147 | Installation of Fuselage Access Panels for Cyclic Trim Actuator Assemblies | 01 Nov 1983 |
| 148 | Field Repair – PN 369A1300-5 Pitch Control Housing Assembly, Main Rotor Hub | 01 Nov 1983 |



MD Helicopters Inc.
 4555 East McDowell Road
 Mesa, Arizona 85215-9734

4. Canceled or Superseded Service Information Letters

- (1). The following is a list of Letters that have been canceled or superseded.
- (2). Updated information, pertinent to the Letter, has been incorporated into the appropriate manuals.
- (3). If the Letter is superseded by another Letter, it will be noted in the Subject column in parenthesis after the description.

| 369H SL369H- OR HL- | SUBJECT | Date CANCELED |
|------------------------------------|--|--------------------------|
| 1 | Chart for Hover Ceiling vs. Temperature – Out of Ground Effect | Prior to 15 Jul 1974 |
| 2 | Cyclic Stick Special Option Grip Kit (P/N 369H90129) | Prior to 15 Jul 1974 |
| 4 | Change in Spares Provisioning New P/N 369A1600-21 Tail Rotor Assembly | Prior to 15 Jul 1974 |
| 5.8 | Exchange Program – Major Helicopter Components (Superseded by HL-62) | 15 Feb 1979 |
| 7 | Cold Weather Fuels | Prior to 15 Jul 1974 |
| 8 | New Oil Level Markings for Main Transmission Sight Gage | Prior to 15 Jul 1974 |
| 9 | New Main Transmission Output Seal, P/N 369A5171 | Prior to 15 Jul 1974 |
| 10 | New Roller Bearings for Main Transmission Assembly, Part Nos, 369A5100-603, -605 and -701 | Prior to 15 Jul 1974 |
| 12 | Care and Feeding of Nickel-Cadmium Batteries | 09 Feb 2004 |
| 13.1 | Improved Window Glass Retention for Pilot and Passenger Door Assemblies | 06 Feb 2004 |
| 20 | Shut Down Procedure – Allison Model 250-C20 Series Engine | 09 Feb 2004 |
| 24 | Cold Weather Torque Adjustment – Main Rotor Damper Assembly PN 369A1400, 369A1400-601 and -603 | 09 Feb 2004 |
| 25 | New Proof-Load Test Requirements for Main Transmission Roller Bearings, 369A5180, 369A5198-3, 369A5199-3 | Prior to 15 Jul 1974 |
| 27 | Corporate Name Change | 22 Nov 1996 |
| 28 | Torque Requirement for Driveshaft Coupling Retainer Bolts PN 369A5528 | 10 Feb 2004 |
| 29 | Installation of Steel Washers – Driven Pulley; Belt-Driven Oil Cooler Blower Assembly | 10 Feb 2004 |
| 33 | Breeze BL-16600-11 Hoist Winch Assembly – Improper Cable Cutter Installation | 11 Feb 2004 |
| 35 | Engine Inlet, Air Particle Separator Filter Installation PN 369H90148 Optional Equipment Availability | 11 Feb 2004 |
| 41 | New Conical Type Teeter Bearings for Tail Rotor Assembly | 12 Feb 2004 |
| 43 | Interim Revision of HMI Appendix C Component Overhaul Manual – Tail Rotor Drive Fork and Hub Assembly Equipped With Conical Type Teeter Bearings | 16 Feb 2004 |
| 45 | New Main Rotor Damper Assembly PN 369A1423-501 | 16 Feb 2004 |
| 48 | Interim Restriction of N2 Operating Speed | 17 Feb 2004 |
| 49 | Power Turbine (N2) Rub or Lockup in 250-C20 Engine | 17 Feb 2004 |
| 50 | New Oil Level Requirement for Initial Installation of Overrunning Clutch, PN 369A5350 Series | 17 Feb 2004 |
| 51 | New PN 369A1100-503 – Main Rotor Blade Assembly With Leading Edge Abrasion Strip | 23 Feb 2004 |
| 52 | Restriction of N2 Operating Speed | 23 Feb 2004 |

Current indexes are available at: www.mdhelicopters.com

MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734



| 369H SL369H- OR HL- | SUBJECT | Date CANCELED |
|---------------------------|--|-------------------------|
| 54 | Unlimited Service Life – PN 369A7010 One-Way Unilock and PN 369A5408 and 369A5408-3 Tail Rotor Output Shafts | 24 Feb 2004 |
| 56 | Transmission, Main and Tail Rotor – Oil Change and Filter Period Extended From 150 Hours to 300 Hours | 02 Mar 2004 |
| 57 | Paint Schedules and Ordering Procedures | 02 Mar 2004 |
| 59 | Reduction Gearbox, Model 250-C20 Engine – Time Between Overhaul (TBO) Requirement Eliminated | 02 Mar 2004 |
| 60 | PN 369A1620 Series Tail Rotor Assembly – Elimination of Overhaul Schedule (TBO) Requirement – Interchangeability of 369A1725 Series Tail Rotor Hub Assembly | 03 Mar 2004 |
| 62.1 | Exchange Program – Major Helicopter Components | Prior to 01 Jul 1981 |
| 63 | Approved Igniter Assemblies and Ignition Exciter Assemblies for Hughes PN 369H90118 Series Automatic Engine Re-ignition Kit Installations | 04 Mar 2004 |
| 65 | New Comfort Clips for Seat Belt and Shoulder Harness Assemblies, PN 369H6541-5 and 369H6541-21 | 01 Nov 1983 |
| 66 | Engine Compressor Cleaning – Daily Water Rinse and Periodic Water Wash | 05 Mar 2004 |
| 68.13 | Exchange Program – Major Helicopter Components (Cancelled, superseded by the Spare Parts, Publications and Component Exchange Price Catalog.) | 01 Jul 1997 |
| 69 | Detroit Diesel Allison Commercial Service Letter CSL-1079, Re: High Pressure Fuel Filter (CECO Fuel System) | 09 Mar 2004 |
| 71.12 | Annual Listing of Airworthiness Directives Affecting MDHS Helicopters (Superseded by SL369H-135) | 23 May 2000 |
| 73 | PN 369A1200 and 369N1200 Main Rotor Hub Assembly PN 369A5100-709 Main Rotor Transmission and PN 369A5400-701 Tail Rotor Transmission – Time Between Overhaul (TBO) Increased | 12 Mar 2004 |
| 74 | Corrosion Control Manual now Available for General Distribution and Purchase | 15 Mar 2004 |
| 77.2 | Summary of FAA Supplemental Type Certificates for all 369 Series Helicopters (Superseded by SL369H-136) | 05 Jun 2000 |
| 79 | Un-Assigned | |
| 81 | Lubrication of Drive End Bearing Liner in Aircraft Parts Corp. Model 150SG Starter-Generator | 19 Mar 2004 |
| 82 | PN 369A7609 Series Main Rotor Swashplate Assembly – Time Between Overhaul (TBO) Increased to 2650 Hours | 22 Mar 2004 |
| 83 | Distribution and Shipment of HHI 269/369 Commercial and Military Publications | 22 Jan 2004 |
| 90 | Service Life Reduction for PN 369A1706 Tension Torsion Strap Assemblies Previously Used on U.S. Army TH-55 Trainer Helicopters | 01 Apr 2004 |
| 92 | Start Pump Wire Routing Precaution (Superseded by HN-210) | 01 Apr 2004 |
| 95.3 | Product Support Department Communication Links | 23 May 2000 |
| 96.1 | Availability of Kamatics Corp. Kaflex Main Driveshaft (MDHC PN 369D25515) and Tail Rotor Drive Shaft Couplings (MDHC PN 369D25501-3) | 06 Apr 2004 |
| 101 | Improved Strength PC Filter Housing | 08 Apr 2004 |
| 103 | Availability and Distribution of Tri-Flow Lubricant/Wash | 13 Apr 2004 |
| 106 | Recommend Replacement Interval for 369H5655-3 & -5 Oil Cooler Bearing and 369H5648 Oil Cooler Belt | 08 Apr 2004 |
| 107 | Improved Fuel Drain Valve Assembly | 12 Apr 2004 |
| 109 | Availability of Spares Price List On Floppy Disk (Superseded by HL-111.1) | 01 Mar 1990 |
| 111.1 | Availability of 1990 Spares Price catalog and Floppy Disk | 17 Dec 1990 |
| 112.1 | New MDHC Authorized Helicopter Airframe Repair Facilities | 07 May 2004 |

Current indexes are available at: www.mdhelicopters.com



MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

| 369H SL369H- OR HL- | SUBJECT | Date CANCELED |
|---------------------------|--|------------------|
| 114.1 | Availability of New Configuration Main Rotor Blade Assemblies – 369D21 10 -515 (369D/E) 369D21102-501 (369F/FF), 369A1100-505 (369H Series) and 369A1100-606 (369A/OH-6A) (Superseded by HN-211.4) | 27 Jan 1993 |
| 115 | Availability of Main Transmission Filler Cap Extension (MDHC PN 369D25112) | 10 May 2004 |
| 117 | Federal Investigation of Central Aviation and Marine Corporation (CAMCO) | 12 May 2004 |
| 118.1 | Availability of Autronics Corporation Electrical Component Exchange Program | 23 Jan 2004 |
| 123.1 | Policy Price of 369H8108 Fuel Vent Line Shutoff Valve | 22 Jan 2004 |
| 127.2 | Introduction of the Use of an Alternate Drive System Lubricant | 10 Nov 2000 |
| 130 | Alternate/Improved Engine Oil Tank Seal | 20 May 2004 |
| 141 | Technical Publications Price Increase | 22 Dec 2010 |

Current indexes are available at: www.mdhelicopters.com



This page intentionally left blank!

Current indexes are available at: www.mdhelicopters.com