



MD900® PUBLICATION INDEXES

CSP-900-INDEX


2006R1.1  
05 June 2006

# **PUBLICATION INDEXES**

for  
**(MDHI Model MD900®)**

## **MD Explorer®**

**Technical Manuals Index**  
**Service Bulletins Index**  
**Technical Bulletins Index**  
**Service Letters Index**



***MD Helicopters Inc.***  
***4555 East McDowell Road***  
***Mesa, Arizona 85215-9734***

IF THE DATE OF THIS PUBLICATIONS INDEX IS OLDER THAN SIX MONTHS,  
CONTACT THE TECHNICAL PUBLICATIONS ORDER DESK TO OBTAIN A CURRENT PUBLICATIONS INDEX.  
TELE: 1-800-388-3378 OR 480-346-6373, FAX: 480-346-6821.  
CURRENT INDEXES ALSO AVAILABLE AT: [www.mdhelicopters.com](http://www.mdhelicopters.com)

**This page intentionally left blank!**



MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

## MODEL MD900® HELICOPTERS (MD EXPLORER®) TECHNICAL MANUAL INDEX

\* COMPLETE REISSUE – SUPERSEDES ALL PREVIOUS ISSUES AND/OR REVISIONS.

# REPRINT – THIS MANUAL HAS BEEN REPRINTED, NEW ORDERS FOR THIS MANUAL NOW CONTAINS THIS REVISION AND ALL PRIOR REVISIONS AND REISSUES. PREVIOUS REVISIONS WILL NO LONGER BE AVAILABLE.

| <b>Rotorcraft Maintenance Manual Instructions (RMM) MD900®</b><br>The MD900® Rotorcraft Maintenance Manual Set consists of the following publications: |  |                     |                   |                 |                  |
|--|--|---------------------|-------------------|-----------------|------------------|
| <b>Publication Number</b>  | <b>Publication Title</b>   | <b>Issue Number</b> | <b>Issue Date</b> | <b>Rev. No.</b> | <b>Rev. Date</b> |
| CSP-A-1  | 2005 Price List, Spare Parts and Tools   | Reissue             | 15 Jul 2005*      |                 |                  |
| CSP-A-2  | Warranty Manual  | Reissue             | 23 Jul 2003 *     | Rev. B          | 22 Feb 2005      |
| CSP-900RMM-2 S1  | Ground Based Maintenance Computer User Guide (GBMC)<br>GBMC Software, Part No. 900G9720002 IIDS<br>Interface Cable, Part No. 900G8930003-101 | Original            | 16 Oct 1996       |                 |                  |
| CSP-900RMM-2 S2  | Ground Based Maintenance Computer User Guide (GBMC)<br>GBMC Software, Part No. 900G9720003 IIDS<br>Interface Cable, Part No. 900G8930003-101 | Original            | 23 Dec 1997       |                 |                  |
| CSP-900RMM-2 S3  | Ground Based Maintenance Computer User Guide (GBMC)<br>Software, Part No. 900G9720004 IIDS<br>Interface Cable, Part No. 900G8930003-101      | Original            | 19 Feb 2001       |                 |                  |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734



### Rotorcraft Maintenance Manual Instructions (RMM) MD900® (Cont.)

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number | Publication Title  | Issue Number | Issue Date    | Rev. No.   | Rev. Date  |
|--------------------|--|--------------|---------------|--|--|
| CSP-SPM            | Standard Practice Manual (to be used in conjunction with CSP-900RMM-2, -3) | Original     | 23 Dec 1997   | Rev. 1<br>Rev. 2<br>Rev. 3<br>Rev. 4<br>Rev. 5<br>Rev. 6<br>Rev. 7<br>Rev. 8<br>Rev. 9<br>Rev. 10<br>Rev. 11<br>Rev. 12<br>Rev. 13<br>Rev. 14  | 22 Apr1998<br>16 Feb 999<br>31 Sep 1999<br>30 Sep 1999<br>29 Feb 2000<br>20 Aug 2000<br>06 Apr 2001<br>08 Apr 2002<br>09 Aug 2002<br>24 Jan 2003<br>20 Jun 2003 #<br>12 Nov 2004<br>14 April 2005<br>26 April 2006   |
| CSP-900RMM-2       | Rotorcraft Maintenance Manual – Servicing and Maintenance                  | Reissue 1    | 24 Dec 1997 * | Rev. 1<br>Rev. 2<br>Rev. 3<br>Rev. 4<br>Rev. 5<br>Rev. 6<br>Rev. 7<br>Rev. 8<br>Rev. 9<br>Rev. 10<br>Rev. 11<br>Rev. 12<br>Rev. 13<br>Rev. 14<br>Rev. 15<br>Rev. 16<br>Rev. 17<br>Rev. 18<br>Rev. 19<br>Rev. 20<br>Rev. 21<br>Rev. 22<br>Rev. 23<br>Rev. 24<br>Rev. 25<br>Rev. 26<br>Rev. 27<br>TR06-002 | 22 Apr 1998<br>24 Jul 1998<br>16 Feb 1999<br>16 May 1999<br>30 Sep 1999<br>30 Dec 1999<br>30 Jun 2000<br>10 Aug 2000<br>10 Nov 2000<br>21 Mar 2001<br>17 Apr 2001<br>18 Jan 2002<br>08 Apr 2002<br>26 Apr 2002<br>28 Jun 2002<br>19 Aug 2002<br>27 Sep 2002<br>23 Jan 2003<br>20 Jun 2003<br>05 Sep 2003<br>05 Dec 2003<br>10 Jun 2004<br>12 Oct 2004<br>04 Nov 2004<br>16 April 2005 #<br>31 Oct 2005<br>26 April 2006<br>15 May 2006 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

**Rotorcraft Maintenance Manual Instructions (RMM) MD900® (Cont.)**

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number             | Publication Title  | Issue Number | Issue Date    | Rev. No.   | Rev. Date  |
|--------------------------------|--|--------------|---------------|--|--|
| CSP-900RMM-3                   | Rotorcraft Maintenance Manual – Instruments / Electrical / Avionics                                      | Reissue 1    | 30 Jan 1998 * | Rev. 1<br>Rev. 2<br>Rev. 3<br>Rev. 4<br>Rev. 5<br>Rev. 6<br>Rev. 7<br>Rev. 8<br>Rev. 9<br>Rev. 10<br>Rev. 11 | 30 May 1998<br>30 Nov 1999<br>12 July 2000<br>10 Aug 2000<br>07 Dec 2000<br>30 Nov 2001<br>08 Apr 2002<br>12 Sep 2002<br>27 Sep 2002<br>20 Jun 2003<br>26 May 2004 # |
| CSP-900IPL-4                   | Illustrated Parts List   | Reissue 2    | 11 Feb 1998 * | Rev. 1<br>Rev. 2<br>Rev. 3<br>Rev. 4<br>Rev. 5<br>Rev. 6<br>Rev. 7<br>Rev. 8<br>Rev. 9<br>Rev. 10            | 30 Jun 1998<br>16 Feb 1999<br>30 Sep 1999<br>09 Mar 2001<br>08 Apr 2002<br>27 Sep 2002<br>24 Jan 2003<br>20 Jun 2003<br>26 May 2004 #<br>27 Apr 2006                 |
| CSP-900SHP-S                   | Shipping Manual  | Original     | 29 Aug 1997   | Rev. 1<br>Rev. 2<br>Rev. 3   | 30 Sep 1999<br>20 Aug 2000<br>10 Apr 2001 #  |
| CSP-900MOD<br>MOD MD9009500001 | Modification Instructions for Forward Fuel Vent (Ref. SB 900-008)  | Original     | 16 Oct 1995   | Rev. 1   | 12 Feb 1996  |
| CSP-900MOD<br>MOD MD9009500003 | Modification Instructions for Vent System Air Duct/Additional Air Outlets Installation (Ref. SB 900-035) | Original     | 26 Jun 1997   |  |  |
| CSP-900MOD<br>MOD MD9009500008 | Modification Instructions for Cockpit and Cabin Doors (Ref. SB 900-007R1)                                | Reissue 1    | 12 Jul 1997 * |  |  |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734



### Rotorcraft Maintenance Manual Instructions (RMM) MD900® (Cont.)

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number             | Publication Title   | Issue Number | Issue Date  | Rev. No.                            | Rev. Date  |
|--------------------------------|---|--------------|-------------|-------------------------------------|--|
| CSP-900MOD<br>MOD MD9009500013 | High Puncture-Resistant<br>Fuel Cell (JAR 27<br>Compliance)<br>(Ref. SB900-020R1) | Original     | 09 May 1996 |                                     |  |
| CSP-RLB                        | Rotorcraft Log Book   | Original     | 01 Dec 1994 | Rev.1<br>Rev. 2<br>Rev. 3<br>Rev. 4 | 18 Apr 1997<br>17 Feb 2000<br>01 Jun 2001<br>31 May 2002 # |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

† RFM Temp Rev to remain in manual until IIDS has been replaced. Ref AD2001-25-51, SB900-081R1.

| <b>Rotorcraft Flight Manual (RFM) MD900®</b><br>The MD900® Rotorcraft Flight Manuals consists of the following publications: |   |              |               |  |  |
|--|---|--------------|---------------|--|--|
| Publication Number   | Publication Title   | Issue Number | Issue Date    | Rev. No.   | Rev. Date  |
| CSP-900RFM206A-1<br>(900 Config w/PW206A)  | Rotorcraft Flight Manual  | Reissue 2    | 26 Feb 2003 * | TR01-001†<br>Rev. 1<br>Rev. 2<br>Rev. 3<br>TR06-001              | 26 Feb 2003<br>29 May 2003<br>31 Oct 2003<br>08 Jul 2005 #<br>05 Jun 2006              |
| CSP-900RFM206A-S1  | Increased Gross Weight Operations, 6251-6500 LB (RFM Supplement to CSP-900RFM206A-1, Serial Number specific) NOT JAA APPROVED                                 | Reissue 1    | 26 Feb 2003 * |  |  |
| CSP-900RFM206A-S2  | Takeoff & Landing Operations (JAR OPS), (RFM Supplement to CSP-900RFM206A-1)<br><b>NOTE:</b> Supplement used by German registered aircraft with LBA approval. | Reissue 1    | 13 Feb 2003 * |  |  |
| CSP-900RFM206E-1<br>(900 Config w/PW206E)  | Rotorcraft Flight Manual  | Reissue 1    | 03 Mar 2003 * | TR01-001†<br>Rev. 1<br>Rev. 2<br>Rev. 3<br>TR06-001              | 03 Mar 2003<br>29 May 2003<br>31 Oct 2003<br>08 Jul 2005<br>05 Jun 2006                |
| CSP-900RFM207E-1<br>(900 Config w/PW207E)  | Rotorcraft Flight Manual  | Original     | 01 Jul 2002   | Rev. 1<br>Rev. 2<br>Rev. 3<br>TR06-001                           | 05 May 2003<br>31 Oct 2003<br>08 Jul 2005<br>05 Jun 2006                               |
| CSP-900RFM207E-S1  | Temperature Increase  |              | Not Approved  |  |  |
| CSP-900RFM207E-S2  | Increased Gross Weight Operations, 6251-6500 LB (RFM Supplement to CSP-900RFM207E-1, Serial Number specific) NOT JAA APPROVED                                 | Original     | 26 Dec 2002   | Rev. 1<br>Rev. 2   | 05 May 2003<br>25 Oct 2005   |
| CSP-902RFM206E-1<br>(902 Config w/PW206E)  | Rotorcraft Flight Manual  | Reissue 2    | 04 Mar 2003 * | TR01-001†<br>TR01-002†<br>Rev. 1<br>Rev. 2<br>Rev. 3<br>TR06-001 | 04 Mar 2003<br>04 Mar 2003<br>29 May 2003<br>31 Oct 2003<br>08 Jul 2005<br>05 Jun 2006 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734



### Rotorcraft Flight Manual (RFM) MD900® (Cont.)

The MD900® Rotorcraft Flight Manuals consists of the following publications:

| Publication Number                        | Publication Title  | Issue Number | Issue Date  | Rev. No.  | Rev. Date   |
|---|--|--------------|-------------|---|---|
| CSP-902RFM207E-1<br>(902 Config w/PW207E) | Rotorcraft Flight Manual   | Original     | 28 Jul 2000 | Rev. 1<br>Rev. 2<br>TR01-001 †<br>TR01-002 †<br>Rev. 3<br>Rev. 4<br>Rev. 5<br>Rev. 6<br>Rev. 7<br>Rev 8<br>TR06-001 | 30 May 2001<br>02 Nov 2001<br>02 Nov 2001<br>28 Nov 2001<br>26 Dec 2002<br>13 Feb 2003<br>23 Apr 2003<br>22 Sep 2003<br>13 Jan 2004<br>08 Jul 2005 #<br>05 Jun 2006 |
| CSP-902RFM207E-S1                         | Increased Gross Weight Operations, 6251-6500 LB (RFM Supplement to CSP-902RFM207E-1, Serial Number specific)<br>NOT JAA APPROVED | Original     | 18 Dec 2002 | Rev. 1<br>Rev. 2<br>Rev. 3<br>Rev. 4  | 23 Apr 2003<br>31 Oct 2003<br>12 July 2004<br>25 Oct 2005 #   |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821





**MD900® PUBLICATION INDEXES**  
**MD Helicopters, Inc.**  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

**CSP-900-INDEX**

**MODEL MD900® HELICOPTERS**  
**(MD EXPLORER®)**  
**SERVICE BULLETIN INDEX**

| <b>MD-900 Service Bulletins</b> |   |                           |   |
|---------------------------------|---|---------------------------|---|
| <b>Publication Number</b>       | <b>Publication Title</b>  | <b>Issue/Reissue Date</b> | <b>Applicable Airworthiness Directive</b>           |
| SB900-102                       | Inceased Gross Weight Capability to 6500 LBS With V <sub>NE</sub> Card and LH Middle Aft Truss Assembly Replacement | 09 May 2006               |   |
| SB900-101                       | Drive Ring Assembly One Time Inspection and Rework  | 21 April 2006             |   |
| SB900-100                       | Directional Pedal Assembly Modification   | 05 April 2006             |   |
| SB900-099                       | Thruster Extension and Vortex Generator Insatllation  | 09 May 2006               |   |
| SB900-098                       | Fuel Probe Label Replacement  | 19 Oct 2005               |   |
| SB900-097                       | Bonded Keel/Tub Modification  | 06 Jun 2005               |   |
| SB900-096                       | Swashplate Spherical Slider Bearing (900C3010042-103) Life Limit Reduction  | 28 Feb 2005               |   |
| SB900-095                       | Tension-Torsion Strap Inspection  | 03 Nov 2004               | 2004-23-15  |
| SB900-094                       | Fan Input Force Limiting Control Rod Assembly, Fail-Safe Device Installation and Pilot's Daily Check                | 17 Mar 2004               | 2004-16-08  |
| SB900-093                       | Main Rotor Drive Plate Nut Torque Check and Torque Increase   | 08 Sep 2003               |   |
| SB900-092R2                     | Main Rotor Blade Retention Bolt Inspection  | 02 Sep 2004               | 2003-14-51  |
| SB900-091                       | Cabin Floor Attach Points Inspection and Rework   | 06 May 2003               |   |
| SB900-090                       | Pilot's Collective Stick Floor Access Cover Rework  | 18 Dec 2002               |   |
| SB900-089R1                     | Main Rotor Support Static Mast, One Time Inspection   | 22 Oct 2002               | 2002-22-51 and Alternate Means of Compliance (AMOC) |
| SB900-088                       | Integrated Instrument Display System (IIDS) Test  | 14 Aug 2002               |   |
| SB900-087                       | Main Rotor Transmission Assembly Upgrade  | 20 Aug 2002               |   |
| SB900-086                       | Modified Empennage Bellcrank Assembly Reidentification  | 17 Jun 2002               |   |
| SB900-085                       | Engine Oil Breather Hose Replacement  | 13 Feb 2002               |   |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



### MD-900 Service Bulletins (Cont.)

| Publication Number | Publication Title  | Issue/Reissue Date | Applicable Airworthiness Directive                           |
|--------------------|--|--------------------|--|
| SB900-084          | Life Limit and Serialization of Lateral Mixer Bellcrank Assemblies   | 03 Dec 2001        | 2002-15-07   |
| SB900-083R1        | Integrated Instrument Display System (IIDS) EEC Light Wiring Modification                                  | 09 Oct 2002        |  |
| SB900-082R2        | Integrated Instrument Display System (IIDS) GEN Light Wiring Modification                                  | 10 Jun 2003        |  |
| SB900-081R1        | Integrated Instrument Display System (IIDS) Replacement  | 08 Nov 2001        | 2001-25-51   |
| SB900-080          | Fuel Contamination Inspection  | 15 May 2001        |  |
| SB900-079R1        | Mechanical Engine Controls – One Time Inspection and Replacement of Pilot and Copilot Collective Sticks    | 19 Mar 2002        |  |
| SB900-078          | Non-Rotating Swashplate Assembly Bushing Rework and Longitudinal Drive Link Assembly Inspection and Repair | 23 Apr 2001        | 2002-23-03   |
| SB900-077          | Inspection and Rework of Aft Deck Splitter Attachment Structure  | 04 Dec 2000        |  |
| SB900-076R1        | Inspection and Rework of Main Rotor Support Static Mast  | 04 Dec 2000        |  |
| SB900-075          | Electrical Load Center Inspection and Rework   | 04 Aug 2000        |  |
| SB900-074          | NACA Support Assembly Replacement and Inspection/Rework of NACA Inlet Assembly                             | 30 Aug 2000        |  |
| SB900-073          | Cargo Hook Installation and Aft Saddle Assemblies Inspection and Replacement of Aft Saddle Assemblies      | 28 Jun 2000        |  |
| SB900-072          | Main Rotor Hub Inspection and Torque Check   | 10 Dec 1999        | 99-26-20<br>and<br>2001-07-09<br>superseded by<br>2002-10-05 |
| SB900-071          | Non-Rotating Swashplate Assembly Bushing Rework and Longitudinal Drive Link Assembly Inspection and Repair | 10 Jan 2000        | 2000-18-08   |
| SB900-070          | Takeoff GO/NO-GO Timer Light Modification  | 24 Apr 2000        |  |
| SB900-069R1        | A612 Forward Interconnect Panel Modification   | 24 Apr 2000        |  |
| SB900-068R1        | Right VSCS Actuator Inboard Rod End Thread Engagement Inspection   | 08 Jul 1999        |  |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



| <b>MD-900 Service Bulletins (Cont.)</b> |   |                           |   |
|---|---|---------------------------|---|
| <b>Publication Number</b>               | <b>Publication Title</b>  | <b>Issue/Reissue Date</b> | <b>Applicable Airworthiness Directive</b>   |
| SB900-067R1                             | Electromagnetic Testing   | 14 Apr 2003               |   |
| SB900-066R1                             | Inspection of Cabin Doors Equipped with Nordam Sliding Window Installations             | 12 Aug 1999               |   |
| SB900-065                               | Main Rotor Hub Inspection   | 09 Jun 1998               | 98-12-30  |
| SB900-064                               | Pedal Attach Plate Inspection   | 18 Jun 1998               |   |
| SB900-063                               | Mechanical Engine Control System Modification   | 15 May 1998               |   |
| SB900-062R1                             | Main Rotor Driveshaft Assembly Life Limitation  | 16 Dec 1999               | 2000-10-06  |
| SB900-061R1                             | Cockpit Door Lower Rod Modification   | 07 Jul 2000               |   |
| SB900-060                               | Cabin Entry/Egress Step Modification  | 23 Jul 1997               |   |
| SB900-059                               | Gradient Springs Rod End Bearing Inspection   | 19 Jan 1998               |   |
| SB900-058R2                             | Life Limit on Anti-Torque Fan Assembly, Tension-Torsion Straps and Pitch Plate Assembly | 10 May 1999               | 99-05-08  |
| SB900-057                               | Self Aligning Spherical/Slider Bearing Life Limit Reduction                             | 05 Jun 1997               |   |
| SB900-056                               | Grounding Notice for All MD900 Operators  | 28 May 1997               | 97-12-02,<br>29 May 1997<br>(Priority Letter)<br>Superseded by<br>97-12-02,<br>2 Dec 1997 |
| SB900-055R1                             | Adjustable Collective Drive Link Serialization and Replacement                          | 05 Jun 1997               | 97-12-02,<br>2 Dec 1997   |
| SB900-054R1                             | Off Gate Diode Modification   | 08 Aug 1997               |   |
| SB900-053                               | Cabin Door Ajar Switch Modification   | 11 Apr 1997               |   |
| SB900-052                               | Cargo Hook Shorting Plug  | 12 May 1997               |   |
| SB900-051                               | Main Rotor Drive Plate Mounting Bolt Inspection   | 18 Apr 1997               |   |
| SB900-050                               | Low Temperature Fuel Additive Placard Modification                                      | 18 Apr 1997               |   |
| SB900-049                               | Main Transmission Retrofit  | 21 Feb 1997               |   |
| SB900-048R1                             | Gradient Spring Assemblies Replacement  | 09 Jan 1998               |   |
| SB900-047                               | VSCS Synchronization Modification   | 30 Jan 1997               |   |
| SB900-046R1                             | Horizontal Stabilizer Drain Holes   | 26 Feb 1997               |   |
| SB900-045R2                             | IIDS Battery Discharge Indication Correction  | 04 Apr 1997               |   |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



### MD-900 Service Bulletins (Cont.)

| Publication Number | Publication Title   | Issue/Reissue Date | Applicable Airworthiness Directive |
|--------------------|---|--------------------|------------------------------------|
| SB900-044R1        | Life Limit on Swashplate Slider Bearing                     | 17 Dec 1996        |                                    |
| SB900-043R1        | Flight Controls Life Limits                                 | 16 Jan 1997        |                                    |
| SB900-042R3        | Hydraulic Manifold/Reservoir Rework                         | 12 Feb 1998        |                                    |
| SB900-041R4        | Manual Engine Start Electrical Modification                 | 14 Oct 2002        |                                    |
| SB900-040          | Cabin and Cockpit Door Latch Housing Replacement            | 29 Oct 1996        |                                    |
| SB900-039 R2       | VSCS Bellcrank and Mid-Aft Strut Serialization              | 12 Mar 1997        | 99-16-13 and 97-13-09              |
| SB900-038          | Main Rotor Hub Retention Bolt Retorque                      | 30 Aug 1996        |                                    |
| SB900-037          | Condenser Fan EMI Filter Installation                       | 12 Aug 1996        |                                    |
| SB900-036R2        | Cyclic Trim Servo 100 Hour Inspection                       | 20 Sep 1999        |                                    |
| SB900-035 R1       | Electrical Panel Modifications                              | 19 Nov 1996        |                                    |
| SB900-034 R2       | Main Rotor Swashplate Bearing Removal from Service          | 19 Nov 1996        | 97-20-12                           |
| SB900-033          | Main Rotor Blade Life Limit Increase                        | 19 Jun 1996        |                                    |
| SB900-032          | Three Part Swashplate Bearing Inspection and Modification   | 05 Jun 1996        |                                    |
| SB900-031 R1       | Swashplate Bearing Retainer Ring Modification               | 01 Jul 1996        |                                    |
| SB900-030 R1       | One-Time Swashplate Bearing Preload Inspection              | 22 May 1996        |                                    |
| SB900-029          | NOTAR® Fan Diffuser Retention Fastener Inspection           | 06 Sep 1996        |                                    |
| SB900-028 R1       | Swashplate Bearing, One-Time Inspection                     | 04 May 1996        |                                    |
| SB900-027          | Rigging Inspection of Vertical Stabilizer Control System    | 09 May 1996        |                                    |
| SB900-026          | Link Assembly, Drive – Scissors, One-Time Inspection        | 09 Apr 1996        |                                    |
| SB900-025          | Ignition Circuit Breaker Replacement                        | 09 May 1996        |                                    |
| SB900-024          | EEC Replacement   | 22 Apr 1996        |                                    |
| SB900-023          | Thruster Rotating Controls Modification                     | 25 Apr 1996        |                                    |
| SB900-022          | VNE Card and Support Installation                           | 09 May 1996        |                                    |
| SB900-021R1        | Endplate Spar Tube (Vertical Stabilizer) Greasing Procedure | 03 Jan 1997        |                                    |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



| <b>MD-900 Service Bulletins (Cont.)</b> |  |                           |   |
|---|--|---------------------------|---|
| <b>Publication Number</b>               | <b>Publication Title</b>   | <b>Issue/Reissue Date</b> | <b>Applicable Airworthiness Directive</b> |
| SB900-020 R1                            | High Puncture-Resistant Fuel Cell Modification (Ref. Mod MD9009500013) | 01 Jul 1996               |   |
| SB900-019                               | Pitot Tube Replacement   | 12 Mar 1996               |   |
| SB900-018 R1                            | Lateral Anti-Torque Drive Link Assembly Installation                   | 24 May 1996               |   |
| SB900-017 R2                            | Batter Warm Disable Relay Installation/Rework                          | 16 Dec 1996               |   |
| SB900-016 R2                            | Aft Cabin Heat Guard Assembly Installation                             | 28 Dec 1996               |   |
| SB900-015                               | Cabin Heater Modification  | 24 May 1996               |   |
| SB900-014                               | Cabin Door D-Ring Replacement  | 23 Feb 1996               |   |
| SB900-013                               | Torque Verification of Blade Retention Bolts                           | 12 Jan 1996               |   |
| SB900-012R1                             | Air Conditioning Condenser Scoop Installation                          | 12 Jul 1997               |   |
| SB900-011                               | Air Vent Scoop Installation  | 05 Feb 1996               |   |
| SB900-010                               | Fuel Metering Unit (FMU) Manual Mode Deceleration Check                | 14 Feb 1996               |   |
| SB900-009                               | Heater Limitation Placard Installation                                 | 14 Dec 1995               |   |
| SB900-008                               | Forward Fuel Vent Modification (Ref. Mod MD9009500001)                 | 14 Dec 1995               |   |
| SB900-007 R1                            | Cockpit and Cabin Door Modifications (Ref. Mod MD9009500008)           | 14 Dec 1995               |   |
| SB900-006                               | Application of Collective Control Index Mark                           | 19 Jul 1995               |   |
| SB900-005                               | Replacement of Generator Control Units (GCU'S)                         | 19 Jul 1995               |   |
| SB900-003 R1                            | Anti-Torque Directional Control Actuator Replacement                   | 29 Jan 1996               |   |
| SB900-002 R1                            | Copilot Collective Stick Removal Restriction                           | 22 Dec 1995               |   |
| SB900-001 R5                            | Flexbeam Inspection  | 27 Aug 1999               |   |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



**This page intentionally left blank!**

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

**MODEL MD900® HELICOPTERS  
(MD EXPLORER®)  
TECHNICAL BULLETIN INDEX**

| MD900 Technical Bulletins |  |                    |
|---------------------------|--|--------------------|
| Publication Number        | Publication Title  | Issue/Reissue Date |
| TB900-026                 | Supplemental Fuel Cell (Check Valve) Modification                | 27 May 2003        |
| TB900-025R2               | Generator Cooling Modification                                   | 14 Aug 2003        |
| TB900-024                 | Cabin Door Modification  | 23 Apr 2003        |
| TB900-023                 | Oil Cooler Inlet Duct Modification                               | 27 Jan 2002        |
| TB900-022                 | Rain Gutter Modification   | 17 Jun 2002        |
| TB900-021                 | Cabin Window Emergency Release Cover Modification                | 26 Feb 2002        |
| TB900-020R2               | Removable Copilot Controls Modification                          | 02 May 2002        |
| TB900-019                 | Range Extender Modification                                      | 30 Aug 2000        |
| TB900-018R2               | Dual Essential Bus Relays Modification                           | 23 Aug 2001        |
| TB900-017                 | Heat/Defog Shutoff Valve Upgrade Modification                    | 26 Jul1999         |
| TB900-016R2               | Dual Pilot to Single Pilot Control Conversion                    | 16 Nov 2000        |
| TB900-015                 | Windscreen Wipers -103 Installation                              | 17 Jun1999         |
| TB900-014R4               | JAR OPS-3 Modification   | 13 Nov 2001        |
| TB900-012R1               | Fire Extinguishing System Installation                           | 09 Feb 2000        |
| TB900-011                 | Landing/Hover Light Relocation Modification                      | 17 Mar 1999        |
| TB900-010R1               | Increased One Engine Inoperative (OEI) Torque Limit Modification | 13 Dec 2001        |
| TB900-009                 | Modification Instructions for Optional 27 Ampere Hour Battery    | 20 Nov 1998        |
| TB900-008                 | NAS1919 and NAS1921 Alternate Fastener with Drive Anvil          | 06 Nov 1998        |
| TB900-007R1               | Main Rotor Blade Root End Abrasion Tape                          | 14 Feb 2001        |
| TB900-006R1               | Main Rotor Blade Pitch Case Abrasion Tape                        | 14 Feb 2001        |
| TB900-005                 | Heat/Defog Upper Deck Through Fitting Modification               | 12 Jan 1998        |
| TB900-004                 | Modification Instructions for NACA Inlet Assembly Installation   | 11 Nov 1997        |
| TB900-003R1               | Tub Shell (Fuselage) Inspection Panels, Modification to Install  | 15 Mar 2002        |
| TB900-002                 | Alternate Nutplate Installation                                  | 11 Nov 1997        |
| TB900-001                 | VSCS Actuator Mounting Bracket Repair                            | 11 Nov 1997        |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734



**This page intentionally left blank!**

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821





MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

**MODEL MD900® HELICOPTERS  
(MD EXPLORER®)  
SERVICE LETTER INDEX**

| MD-900 Service Letters |                    |                    |   |
|------------------------|--------------------|--------------------|---|
|                        | Publication Number | Issue/Reissue Date | Publication Title   |
|                        | SL900-053          | 13 Sep 2005        | Anti-Torque Control Pedal Separation  |
|                        | SL900-052          | 29 Mar 2005        | Calculation Of One Engine Inoperative (OEI) Excursions Cumulative Log Time For 900A3720002-113 and 900A3720002-121 IIDS |
|                        | SL900-051          | 17 Sep 2003        | Availability of MDHI Publications in Electronic Format  |
|                        | SL900-050          | 21 Mar 2003        | Integrated Instrumentation Display System (IIDS) Mod 3  |
|                        | SL900-049          | 10 Dec 2002        | Prolonging the Life of the Integrated Instrument Display (IIDS)   |
|                        | SL900-048          | 17 Sep 2002        | Availability of New Engine Alignment Tool   |
|                        | SL900-047          | 02 Mar 2001        | New Standard Warranty Statement   |
|                        | SL900-045          | 29 Jun 2000        | Anti-Torque Fan Inlet Screen  |
|                        | SL900-044R1        | 26 Jun 2000        | Availability of Federal Aviation Administration Supplemental Type Certificates for MD Helicopters                       |
|                        | SL900-043          | 23 May 2000        | Availability of Federal Aviation Administration Airworthiness Directives Affecting MD Helicopters                       |
|                        | SL900-042R1        | 14 Jan 2002        | Integrated Instrumentation Display System (IIDS)  |
|                        | SL900-041          | 19 Feb1999         | Transfer of Ownership   |
|                        | SL900-040          | 13 Oct 1998        | Structural Load Limits of MD900 Fuselage Handles  |
|                        | SL900-038          | 13 Feb 1998        | Service Bulletin/Letter Designation   |
|                        | SL900-036R1        | 10 Mar 2000        | Electronic Engine Control – P&WC S.B. 28111   |
|                        | SL900-035          | 26 Jun 1997        | Vent System Air/Duct Addition Air Outlets Installation (Ref. Mod 9009500003)  |
|                        | SL900-033          | 14 May 1997        | Aft Jack Pad Access Hole  |
|                        | SL900-032          | 05 May 1997        | Strobe Light Circuit Breaker Change   |
|                        | SL900-029          | 17 Mar 1997        | Baggage Compartment Closeout Panel Installation for Utility Interiors   |
|                        | SL900-025R1        | 23 Jan 1998        | Cabin Door Handle Installation  |
|                        | SL900-024          | 03 Jan 1997        | Baggage Door Window Installation  |
|                        | SL900-021R1        | 03 Jan 1997        | Four Point Passenger Restraint System   |
|                        | SL900-020R1        | 03 Jan 1997        | Hoist Inspection Hole Installation  |
|                        | SL900-019          | 20 Dec 1996        | Station 203 Ground Handling Hardware  |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

**MD-900 Service Letters (Cont.)**

| <b>Publication Number</b> | <b>Issue/Reissue Date</b> | <b>Publication Title</b>                                |
|---------------------------|---------------------------|---|
| SL900-018                 | 18 Dec 1996               | Pedal Friction Hardware Option                          |
| SL 900-016                | 14 Aug 1996               | Secondary Oil Ejector Modification                      |
| SL 900-015                | 08 Jul 1996               | Fastener Hardware Upgrade                               |
| SL 900-014                | 21 May 1996               | Trim Actuator Replacement                               |
| SL 900-013R1              | 21 Mar 1997               | Alternate Floor Panel Hardware Usage                    |
| SL 900-011                | 05 Apr 1996               | Cockpit Door Latch Mechanism Modification               |
| SL 900-010                | 19 Jan 1996               | Integrated Instrumentation Software Upgrade             |
| SL 900-009                | 06 Dec 1995               | Directional Control Inputs Information                  |
| SL 900-007                | 22 Sep 1995               | Aircraft Modification Limitations and STC Installations |
| SL 900-006                | 11 Nov 1995               | Pedal Return Springs                                    |
| SL 900-005                | 11 Nov 1995               | Improved Rig Pin Access FOD Covers                      |
| SL 900-003                | 15 May 1995               | Ground Handling Precautions                             |
| SL 900-002R1              | 22 Jun 2000               | P&WC Publications Distribution Information              |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734

**MODEL MD900® HELICOPTERS  
(MD EXPLORER®)  
CANCELED PUBLICATIONS INDEX**

| Canceled Rotorcraft Maintenance Manual Instructions (RMM) MD900® |               |  |
|--|---------------|--|
| Publication Number   | Date Canceled | Publication Title  |
| CSP-900CMM-5<br>STC1   | 27 Sep 2002   | 600# Rescue Hoist Kit (REF.: P/N 900FG000004) (Superseded by CSP-900RMM-2, Rev 17. CSP-900RMM-3, Rev 9, CSP-900IPL-4, Rev 6) |
| CSP-900WIR-8   | 30 Jan 1998   | Aircraft Wiring Manual (Superseded by CSP-900RMM-3)  |

| Canceled Rotorcraft Flight Manuals (RFM) MD900® |               |  |
|---|---------------|--|
| Publication Number                              | Date Canceled | Publication Title  |
| CSP-900RFM-1                                    | 26 Feb 2003   | Rotorcraft Flight Manual ( <b>900 Config w/ PW206A</b> ) (Superseded by CSP-900RFM206A-1)  |
| CSP-900RFM-S0                                   | 26 Feb 2003   | Belgian Helicopters, RFM Supplement to CSP-900RFM-1 (900 Config w/ PW206A) (Superseded by CSP-900RFM206A-S1)   |
| CSP-900RFM-S1                                   | 12 Mar 2003   | 6500 LB Gross Weight Operations Supplement, RFM Supplement to CSP-900RFM-1 (900 Config w/ PW206A Serial Number specific) (Superseded by CSP-900RFM206A-S1) |
| CSP-900RFM-S2                                   | 12 Mar 2003   | Takeoff & Landing Operations (JAR OPS), RFM Supplement to CSP-900RFM-1 (900 Config w/ PW206A) (Superseded by CSP-900RFM206A-S2)                            |
| CSP-900ERFM-1                                   | 12 Mar 2003   | Rotorcraft Flight Manual ( <b>900 Config w/ PW206E</b> , SN 0041 & 0042 Only) (Superseded by CSP-900RFM206E-1)   |
| CSP-902RFM-1                                    | 12 Mar 2003   | Rotorcraft Flight Manual ( <b>902 Config w/ PW206E</b> ) (Superseded by CSP-902RFM206E-1)  |
| CSP-900RFM207E-S1                               | N/A           | Not Issued   |

| Canceled MD900® Service Bulletins |               |   |
|-----------------------------------|---------------|---|
| Publication Number                | Date Canceled | Publication Title   |
| SB900-004                         | 22 Apr 1996   | Electronic Engine Control (EEC) Replacement (Superseded by SB900-024) |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

MD Helicopters, Inc.  
4555 East McDowell Road  
Mesa, Arizona 85215-9734



### Canceled MD900® Technical Bulletins

| Publication Number | Date Canceled | Publication Title |
|--------------------|---------------|-------------------|
| TB900-013          |               | Not Issued        |

### Canceled MD900® Service Letters

| Publication Number | Date Canceled | Publication Title  |
|--------------------|---------------|--|
| SL 900-001         | 26 Jan 2004   | Chip Light Indication Reporting  |
| SL 900-004         | 27 Jan 2004   | Engine Starting  |
| SL 900-008         | 28 Jan 2004   | Alternate Cyclic Grip  |
| SL 900-012         | 29 Jan 2004   | IIDS Lamp Replacement  |
| SL 900-017         | 29 Jan 2004   | IIDS Phase 2 Implementation  |
| SL900-022R2        | 29 Jan 2004   | Main Rotor Blade Root End Abrasion Tape (Superseded by TB900-007)                                    |
| SL900-023R1        | 17 Jun 2002   | Rain Gutter Modification (Superseded by TB900-022)   |
| SL900-026          | 26 Feb 2002   | Cabin Window Emergency Release Cover (Superseded by TB900-021)                                       |
| SL900-027R1        | 30 Jan 2004   | Main Transmission Retrofit Program   |
| SL900-028R1        | 30 Jan 2004   | Autopilot/SAS Procedural Changes for Bendix/King IFR and VFR Avionics/KFC 900 Flight Control Systems |
| SL900-030          | 27 Jan 2002   | Optional Installation of Access Holes to RH and LH Oil Cooling Inlet Ducts (Superseded by TB900-023) |
| SL900-031          | 30 Jan 2004   | Simulated EEC Failures Manual Mode Training  |
| SL900-034          | 30 Jan 2004   | Non-Rotating Swashplate Life Extension   |
| SL900-037          | 19 Jan 2004   | Primary Exhaust Nozzle Inspection  |
| SL900-039          | 02 Feb 2004   | Main Rotor Hub Inspection (Superseded by SB900-065)  |
| SL900-046R1        | 29 Oct 2001   | Approved Electronic Engine Control (EEC) and Integrated Instrument Display (IIDS) Part Numbers       |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821