


PUBLICATION INDEXES

for
(MDHI Model MD900[®])

MD Explorer[®]

Technical Manuals Index
Service Bulletins Index
Technical Bulletins Index
Service Letters Index



*MD Helicopters Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734*

The hard copy distribution of publications, to subscribers of the MDHI Technical Manuals in paper format (hard copy), can take 90 days or more from the publication date of the document

If the date of this publications index is older than six months, contact MDHI Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821. Current indexes also available at: www.mdhelicopters.com

This page intentionally left blank!



MD Helicopters, Inc.
 4555 East McDowell Road
 Mesa, Arizona 85215-9734

**MODEL MD900® HELICOPTERS
 (MD EXPLORER®)
 TECHNICAL MANUAL INDEX**

* COMPLETE REISSUE - SUPERSEDES ALL PREVIOUS ISSUES AND/OR REVISIONS.

REPRINT - THIS MANUAL HAS BEEN REPRINTED, NEW ORDERS FOR THIS MANUAL NOW CONTAINS THIS REVISION AND ALL PRIOR REVISIONS AND REISSUES. PREVIOUS REVISIONS WILL NO LONGER BE AVAILABLE.

| Rotorcraft Maintenance Manual Instructions (RMM) | | | | | |
|--|--|---------------------|-------------------|-----------------|------------------|
| The MD900® Rotorcraft Maintenance Manual Set consists of the following publications: | | | | | |
| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
| CSP-A-1 | 2005 Price List, Spare Parts and Tools | Reissue | 15 Jul 2005* | | |
| CSP-A-2 | Warranty Manual | Reissue | 23 Jul 2003* | Rev. B | 22 Feb 2005 |
| CSP-900RMM-2 S1 | Ground Based Maintenance Computer User Guide (GBMC) GBMC Software, Part No. 900G9720002 IIDS Interface Cable, Part No. 900G8930003-101 (used with P&WC 206A) | Original | 16 Oct 1996 | | |
| CSP-900RMM-2 S2 | Ground Based Maintenance Computer User Guide (GBMC) GBMC Software, Part No. 900G9720003 IIDS Interface Cable, Part No. 900G8930003-101 (used with P&WC 206E) | Original | 23 Dec 1997 | | |
| CSP-900RMM-2 S3 | Ground Based Maintenance Computer User Guide (GBMC) Software, Part No. 900G9720004 IIDS Interface Cable, Part No. 900G8930003-101 (used with P&WC 207E) | Original | 19 Feb 2001 | | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



Rotorcraft Maintenance Manual Instructions (RMM) (Cont.)

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------|---|--------------|-------------|--|---|
| CSP-SPM | Standard Practice Manual (used with CSP-900RMM-2, -3) | Original | 23 Dec 1997 | Rev. 1 Rev. 2 Rev. 3 Rev. 4 Rev. 5 Rev. 6 Rev. 7 Rev. 8 Rev. 9 Rev. 10 Rev. 11 Rev. 12 Rev. 13 Rev. 14 Rev. 15 Rev. 16 Rev. 17 | 22 Apr1998 16 Feb 999 31 Sep 1999 30 Sep 1999 29 Feb 2000 20 Aug 2000 06 Apr 2001 08 Apr 2002 09 Aug 2002 24 Jan 2003 20 Jun 2003 12 Nov 2004 14 Apr 2005 26 Apr 2006 13 Sep 2006 01 Feb 2007 21 Jul 2008 # |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

Rotorcraft Maintenance Manual Instructions (RMM) (Cont.)

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------|---|--------------|--------------|----------|---------------|
| CSP-900RMM-2 | Rotorcraft Maintenance Manual – Servicing and Maintenance | Reissue 1 | 24 Dec 1997* | Rev. 1 | 22 Apr 1998 |
| | | | | Rev. 2 | 24 Jul 1998 |
| | | | | Rev. 3 | 16 Feb 1999 |
| | | | | Rev. 4 | 16 May 1999 |
| | | | | Rev. 5 | 30 Sep 1999 |
| | | | | Rev. 6 | 30 Dec 1999 |
| | | | | Rev. 7 | 30 Jun 2000 |
| | | | | Rev. 8 | 10 Aug 2000 |
| | | | | Rev. 9 | 10 Nov 2000 |
| | | | | Rev. 10 | 21 Mar 2001 |
| | | | | Rev. 11 | 17 Apr 2001 |
| | | | | Rev. 12 | 18 Jan 2002 |
| | | | | Rev. 13 | 08 Apr 2002 |
| | | | | Rev. 14 | 26 Apr 2002 |
| | | | | Rev. 15 | 28 Jun 2002 |
| | | | | Rev. 16 | 19 Aug 2002 |
| | | | | Rev. 17 | 27 Sep 2002 |
| | | | | Rev. 18 | 23 Jan 2003 |
| | | | | Rev. 19 | 20 Jun 2003 |
| | | | | Rev. 20 | 05 Sep 2003 |
| | | | | Rev. 21 | 05 Dec 2003 |
| | | | | Rev. 22 | 10 Jun 2004 |
| | | | | Rev. 23 | 12 Oct 2004 |
| | | | | Rev. 24 | 04 Nov 2004 |
| | | | | Rev. 25 | 16 Apr 2005 |
| | | | | Rev. 26 | 31 Oct 2005 |
| | | | | Rev. 27 | 26 Apr 2006 |
| | | | | Rev. 28 | 14 Sep 2006 |
| | | | | Rev. 29 | 02 Feb 2007 |
| | | | | Rev. 30 | 06 Apr 2007 |
| | | | | Rev. 31 | 03 Mar 2008 |
| | | | | Rev. 32 | 21 Jul 2008 |
| | | | | Rev. 33 | 13 Feb 2009 |
| TR09-001 | 05 May 2009 | | | | |
| TR09-002 | 25 Jan 2010 | | | | |
| TR09-003 | 27 Oct 2009 | | | | |
| TR09-004 | 09 Nov 2009 | | | | |
| TR09-005 | 23 Dec 2009 | | | | |
| TR09-006 | 27 Jan 2010 | | | | |
| TR10-001 | 28 Jan 2010 | | | | |
| TR10-002 | 02 Feb 2010# | | | | |
| CSP-900RMM-3 | Rotorcraft Maintenance Manual – Instruments / Electrical / Avionics | Reissue 1 | 30 Jan 1998* | Rev. 1 | 30 May 1998 |
| | | | | Rev. 2 | 30 Nov 1999 |
| | | | | Rev. 3 | 12 July 2000 |
| | | | | Rev. 4 | 10 Aug 2000 |
| | | | | Rev. 5 | 07 Dec 2000 |
| | | | | Rev. 6 | 30 Nov 2001 |
| | | | | Rev. 7 | 08 Apr 2002 |
| | | | | Rev. 8 | 12 Sep 2002 |
| | | | | Rev. 9 | 27 Sep 2002 |
| | | | | Rev. 10 | 20 Jun 2003 |
| | | | | Rev. 11 | 26 May 2004 |
| | | | | Rev. 12 | 31 Jan 2007 # |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

Rotorcraft Maintenance Manual Instructions (RMM) (Cont.)

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------------------|--|--------------|--------------|--|---|
| CSP-900IPL-4 | Illustrated Parts List | Reissue 2 | 11 Feb 1998* | Rev. 1 Rev. 2 Rev. 3 Rev. 4 Rev. 5 Rev. 6 Rev. 7 Rev. 8 Rev. 9 Rev. 10 Rev. 11 Rev. 12 Rev. 13 Rev. 14 Rev. 15 | 30 Jun 1998 16 Feb 1999 30 Sep 1999 09 Mar 2001 08 Apr 2002 27 Sep 2002 24 Jan 2003 20 Jun 2003 26 May 2004 27 Apr 2006 19 June 2007 08 May 2009 10 July 2009 25 Sep 2009 23 Dec 2009 # |
| CSP-900SHP-S | Shipping Manual | Original | 29 Aug 1997 | Rev. 1 Rev. 2 Rev. 3 Rev. 4 | 30 Sep 1999 20 Aug 2000 10 Apr 2001 16 Oct 2006 # |
| CSP-900MOD MOD MD9009500001 | Modification Instructions for Forward Fuel Vent (Ref. SB 900-008) | Original | 16 Oct 1995 | Rev. 1 | 12 Feb 1996 |
| CSP-900MOD MOD MD9009500003 | Modification Instructions for Vent System Air Duct/Additional Air Outlets Installation (Ref. SL 900-035) | Original | 26 Jun 1997 | | |
| CSP-900MOD MOD MD9009500008 | Modification Instructions for Cockpit and Cabin Doors (Ref. SB 900-007R1) | Reissue 1 | 12 Jul 1997* | | |
| CSP-900MOD MOD MD9009500013 | High Puncture-Resistant Fuel Cell (JAR 27 Compliance) (Ref. SB900-020R1) | Original | 09 May 1996 | | |
| CSP-900MOD MOD MD9000700001 | MD900 (900 Configuration) To MD900 (902 Configura- tion With PW207E Engines) Change (MDHI restricted use, must be MDHI approved for each helicopter) (Ref. TB900-028) | Original | 20 Dec 2007 | Rev. 1 Rev. 2 Rev.3 | 28 Mar 2008 24 Jun 2008 01 April 2009 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

Rotorcraft Maintenance Manual Instructions (RMM) (Cont.)

The MD900® Rotorcraft Maintenance Manual Set consists of the following publications:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--------------------------------|---|--------------|-------------|-------------------------------------|--|
| CSP-900MOD MOD MD9000700003 | Supplemental Fuel System Installation (MDHI restricted use, must be MDHI approved for each helicopter) (Ref. TB900-030) | Original | 19 Feb 2008 | | |
| CSP-RLB | Rotorcraft Log Book | Original | 01 Dec 1994 | Rev.1 Rev. 2 Rev. 3 Rev. 4 | 18 Apr 1997 17 Feb 2000 01 Jun 2001 31 May 2002 # |
| CSP-900-S1 | Universal Nose Mount | Original | 25 Jun 2005 | | |
| CSP-900-S2 | Airborne Surveillance, Avionics & Mission Equipment | Reissue 1 | 07 Dec 2007 | | |
| CSP-900-S3 | Baggage Compartment Tracks | Original | 8 Apr 2002 | | |
| CSP-900-S4 | Airframe Fuel Filter | Original | 8 Apr 2002 | | |
| CSP-900-S5 | Aft Equipment Shelf | Original | 8 Apr 2002 | | |
| CSP-900-S6 | PBW Airborne Surveillance, Avionics & Mission Equipment (Government restricted to the German Police and IPCAL) | Original | 10 Dec 2002 | | |

Rotorcraft Flight Manual (RFM)

The MD900® Rotorcraft Flight Manuals consists of the following publications:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|---|---|--------------|--------------|---|---|
| CSP-900RFM206A-1 (900 Config/PW206A) | Rotorcraft Flight Manual | Reissue 2 | 26 Feb 2003* | Rev.1 Rev. 2 Rev. 3 Rev. 4 Rev. 5 Rev. 6 | 29 May 2003 31 Oct 2003 08 Jul 2005 21 Aug 2007 20 Feb 2008# 21 Jul 2009 |
| CSP-900RFM206A-S1 | The data in this supplement is now included in CSP-900RFM206A-1 | | | | Canceled |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



Rotorcraft Flight Manual (RFM) (Cont.)

The MD900® Rotorcraft Flight Manuals consists of the following publications:

| Publication Number | Publication Title | Issue Number | Issue Date | Rev. No. | Rev. Date |
|--|---|--------------|--------------|--|--|
| CSP-900RFM206A-S2 | Takeoff & Landing Operations (JAR OPS), (RFM Supplement to CSP-900RFM206A-1) NOTE: Supplement used by German registered aircraft with LBA approval. | Reissue 1 | 13 Feb 2003* | | |
| CSP-900RFM206E-1 (900 Config/PW206E) | Rotorcraft Flight Manual | Reissue 1 | 03 Mar 2003* | Rev. 1 Rev. 2 Rev. 3 Rev. 4 Rev. 5 Rev. 6 | 29 May 2003 31 Oct 2003 08 Jul 2005 21 Aug 2007 20 Feb 2008 # 21 Jul 2009 |
| CSP-900RFM207E-1 (900 Config/PW207E) | Rotorcraft Flight Manual | Original | 01 Jul 2002 | Rev. 1 Rev. 2 Rev. 3 Rev. 4 Rev. 5 Rev. 6 | 05 May 2003 31 Oct 2003 08 Jul 2005 21 Aug 2007 20 Feb 2008 # 21 Jul 2009 |
| CSP-900RFM207E-S1 | Temperature Increase | | Not Approved | | |
| CSP-900RFM207E-S2 (902 Config/PW207E) | Flight Operations in CIS Countries | Original | 12 Dec 2008 | -- | -- |
| CSP-902RFM206E-1 (902 Config/PW206E) | Rotorcraft Flight Manual | Reissue 3 | 06 Nov 2009* | Original | 06 Nov 2009 |
| CSP-902RFM207E-1 (902 Config/PW207E) | Rotorcraft Flight Manual | Reissue 2 | 06 Nov 2009* | Original | 06 Nov 2009 |
| CSP-902RFM207E-S1 | The data in this supplement is now included in CSP-902RFM207E-1 | | | | Canceled |
| CSP-902RFM207E-S2 | Flight Operations in CIS Countries | Original | 12 Dec 2008 | Original | 12 Dec 2008 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



**MODEL MD900® HELICOPTERS
(MD EXPLORER®)
SERVICE BULLETIN INDEX**

| Service Bulletins | | | |
|---------------------------|--|---------------------------|---|
| Publication Number | Publication Title | Issue/Reissue Date | Applicable Airworthiness Directive |
| SB900-114 | One-Time Inspection of Fuel Cell Cord Routing | 17 Nov 2009 | |
| SB900-113 | One-Time Inspection of Oil Out Hoses | 4 Sep 2009 | |
| SB900-112 | Main Rotor Upper Hub and Drive Plate Inspection | 24 Apr 2009 | |
| SB900-111 | Horizontal Endplate (Vertical Stabilizer) Installation | 11 Apr 2009 | |
| SB900-110R1 | Operational Restrictions and Replacement of VSCS Tube Adapters | 03 Dec 2008 | |
| SB900-109R1 | De-Energize VSCS System and Replace VSCS Tube Adapters | 22 Aug 2008 | 2008-18-51 |
| SB900-108R1 | Forward Directional Control Cable and Rotating Cone Control Rod Installation Modification | 13 Aug 2008 | 2008-17-51 |
| SB900-107R1 | NOTAR® Fan Tension-Torsion (TT) Strap Replacement | 14 Mar 2008 | |
| SB900-106 | Forward Directional Control Cable Installation and Rotating Cone Control Rod, One Time Inspection | 20 Dec 2007 | |
| SB900-105 | Rotating Swashplate Life Limit Change and Better Helicopter Performance | 06 Mar 2008 | |
| SB900-104 | Main Rotor Hub Damper Inspection and Replacement | 06 Aug 2007 | |
| SB900-103 | Upper Deck Control Rod Installation One Time Inspection | 05 Nov 2007 | |
| SB900-102R1 | Increased Gross Weight Capability to 6500 LBS With V _{NE} Card and LH Middle Aft Truss Assembly Replacement | 27 Dec 2006 | |
| SB900-101R1 | Drive Ring Assembly One Time Inspection and Rework | 01 Feb 2008 | |
| SB900-100 | Directional Pedal Assembly Modification | 05 Apr 2006 | 2008-08-11 |
| SB900-099R1 | Thruster Extension and Vortex Generator Installation | 27 Dec 2006 | 2009-07-13 |
| SB900-098 | Fuel Probe Label Replacement | 19 Oct 2005 | |
| SB900-097 | Bonded Keel/Tub Modification | 06 Jun 2005 | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

| Service Bulletins (Cont.) | | | |
|----------------------------------|---|---------------------------|---|
| Publication Number | Publication Title | Issue/Reissue Date | Applicable Airworthiness Directive |
| SB900-096 | Swashplate Spherical Slider Bearing (900C3010042-103) Life Limit Reduction | 28 Feb 2005 | |
| SB900-095 | Tension-Torsion Strap Inspection | 03 Nov 2004 | 2004-23-15 superseded by 2006-18-01 |
| SB900-094 | Fan Input Force Limiting Control Rod Assembly, Fail-Safe Device Installation and Pilot's Daily Check | 17 Mar 2004 | 2004-16-08 |
| SB900-093 | Main Rotor Drive Plate Nut Torque Check and Torque Increase | 08 Sep 2003 | |
| SB900-092R2 | Main Rotor Blade Retention Bolt Inspection | 02 Sep 2004 | 2003-14-51 |
| SB900-091 | Cabin Floor Attach Points Inspection and Rework | 06 May 2003 | |
| SB900-090 | Pilot's Collective Stick Floor Access Cover Rework | 18 Dec 2002 | |
| SB900-089R1 | Main Rotor Support Static Mast, One Time Inspection | 22 Oct 2002 | 2002-22-51 and Alternate Means of Compliance (AMOC) |
| SB900-088 | Integrated Instrument Display System (IIDS) Test | 14 Aug 2002 | |
| SB900-087 | Main Rotor Transmission Assembly Upgrade | 20 Aug 2002 | |
| SB900-086 | Modified Empennage Bellcrank Assembly Reidentification | 17 Jun 2002 | |
| SB900-085 | Engine Oil Breather Hose Replacement | 13 Feb 2002 | |
| SB900-084 | Life Limit and Serialization of Lateral Mixer Bellcrank Assemblies | 03 Dec 2001 | 2002-15-07 |
| SB900-083R2 | Integrated Instrument Display System (IIDS) EEC Light Wiring Modification | 15 Sep 2006 | |
| SB900-082R2 | Integrated Instrument Display System (IIDS) GEN Light Wiring Modification | 10 Jun 2003 | |
| SB900-081R1 | Integrated Instrument Display System (IIDS) Replacement | 08 Nov 2001 | 2001-25-51 |
| SB900-080 | Fuel Contamination Inspection | 15 May 2001 | |
| SB900-079R1 | Mechanical Engine Controls - One Time Inspection and Replacement of Pilot and Copilot Collective Sticks | 19 Mar 2002 | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



| Service Bulletins (Cont.) | | | |
|----------------------------------|--|---------------------------|--|
| Publication Number | Publication Title | Issue/Reissue Date | Applicable Airworthiness Directive |
| SB900-078 | Non-Rotating Swashplate Assembly Bushing Rework and Longitudinal Drive Link Assembly Inspection and Repair | 23 Apr 2001 | 2002-23-03 |
| SB900-077 | Inspection and Rework of Aft Deck Splitter Attachment Structure | 04 Dec 2000 | |
| SB900-076R1 | Inspection and Rework of Main Rotor Support Static Mast | 04 Dec 2000 | |
| SB900-075 | Electrical Load Center Inspection and Rework | 04 Aug 2000 | |
| SB900-074 | NACA Support Assembly Replacement and Inspection/Rework of NACA Inlet Assembly | 30 Aug 2000 | |
| SB900-073 | Cargo Hook Installation and Aft Saddle Assemblies Inspection and Replacement of Aft Saddle Assemblies | 28 Jun 2000 | |
| SB900-072 | Main Rotor Hub Inspection and Torque Check | 10 Dec 1999 | 99-26-20 and 2001-07-09 superseded by 2002-10-05 |
| SB900-071 | Non-Rotating Swashplate Assembly Bushing Rework and Longitudinal Drive Link Assembly Inspection and Repair | 10 Jan 2000 | 2000-18-08 |
| SB900-070 | Takeoff GO/NO-GO Timer Light Modification | 24 Apr 2000 | |
| SB900-069R1 | A612 Forward Interconnect Panel Modification | 24 Apr 2000 | |
| SB900-068R1 | Right VSCS Actuator Inboard Rod End Thread Engagement Inspection | 08 Jul 1999 | |
| SB900-067R1 | MD900 Electromagnetic Compatibility (EMC) Test | 14 Apr 2003 | |
| SB900-066R1 | Inspection of Cabin Doors Equipped with Nordam Sliding Window Installations | 12 Aug 1999 | |
| SB900-065 | Main Rotor Hub Inspection | 09 Jun 1998 | 98-12-30 |
| SB900-064 | Pedal Plate Inspection, Directional Controls | 18 Jun 1998 | |
| SB900-063 | Mechanical Engine Control System Modification | 15 May 1998 | |
| SB900-062R1 | Main Rotor Driveshaft Assembly Life Limitation | 16 Dec 1999 | 2000-10-06 |
| SB900-061R1 | Cockpit Door Lower Rod Modification | 07 Jul 2000 | |
| SB900-060 | Cabin Entry/Egress Step Modification | 23 Jul 1997 | |
| SB900-059 | Gradient Springs Rod End Bearing Inspection | 19 Jan 1998 | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

| Service Bulletins (Cont.) | | | |
|----------------------------------|---|---------------------------|---|
| Publication Number | Publication Title | Issue/Reissue Date | Applicable Airworthiness Directive |
| SB900-058R2 | Life Limit on Anti-Torque Fan Assembly, Tension-Torsion Straps and Pitch Plate Assembly and Serialization of Pitch Plate Assemblies | 10 May 1999 | 99-05-08 |
| SB900-057 | Self Aligning Spherical/Slider Bearing Life Limit Reduction | 05 Jun 1997 | |
| SB900-056 | Grounding Notice for All MD900 Operators | 28 May 1997 | 97-12-02, 29 May 1997 (Priority Letter) superseded by 97-12-02, 2 Dec 1997 |
| SB900-055R1 | Adjustable Collective Drive Link Replacement | 05 Jun 1997 | 97-12-02, 2 Dec 1997 |
| SB900-054R1 | Off Gate Diode Installation Modification | 08 Aug 1997 | |
| SB900-053 | Cabin Door Ajar Switch Bracket Rework | 11 Apr 1997 | |
| SB900-052 | Cargo Hook Shorting Plug Installation | 12 May 1997 | |
| SB900-051 | Main Rotor Drive Plate Mounting Bolt Inspection | 18 Apr 1997 | |
| SB900-050 | Operating Temperature Limitation Placard Modification | 18 Apr 1997 | |
| SB900-049 | Main Transmission Retrofit | 21 Feb 1997 | |
| SB900-048R1 | Gradient Spring Assemblies Replacement | 09 Jan 1998 | |
| SB900-047 | VSCS Synchronization Modification | 30 Jan 1997 | |
| SB900-046R1 | Horizontal Stabilizer Drain Holes | 26 Feb 1997 | |
| SB900-045R2 | IIDS Battery Discharge Indication Correction | 04 Apr 1997 | |
| SB900-044R1 | Swashplate Spherical Bearing, Self Aligning | 17 Dec 1996 | |
| SB900-043R1 | Flight Controls Life Limit Changes | 16 Jan 1997 | |
| SB900-042R3 | Hydraulic Manifold/Reservoir Rework | 12 Feb 1998 | |
| SB900-041R4 | Manual Engine Start Electrical Modification | 14 Oct 2002 | |
| SB900-040 | Cockpit and Cabin Door Housing Replacement | 29 Oct 1996 | |
| SB900-039R2 | VSCS Bellcrank, Mid-Aft Strut and Deck Fitting Serialization | 12 Mar 1997 | 99-16-13 and 97-13-09 |
| SB900-038 | Main Rotor Hub Retention Bolt Torque Verification | 30 Aug 1996 | |
| SB900-037 | Condenser Fan EMI Filter Installation | 12 Aug 1996 | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



| Service Bulletins (Cont.) | | | |
|----------------------------------|---|---------------------------|---|
| Publication Number | Publication Title | Issue/Reissue Date | Applicable Airworthiness Directive |
| SB900-036R2 | B.F. Goodrich Trim Servo 300 Hour Inspection | 20 Sep 1999 | |
| SB900-035R1 | Forward Interconnect Panel Modification; Landing Light Circuit Breaker Relocation; Rotor Brake Circuit Breaker Removal | 19 Nov 1996 | |
| SB900-034R2 | Main Rotor Swashplate Bearing, Removal from Service | 19 Nov 1996 | 97-20-12 |
| SB900-033 | Main Rotor Blade Life Limit Increase | 19 Jun 1996 | |
| SB900-032 | Swatchplate Bearing Outer Race Preload, Inspection and Modification Bearing Replacement | 05 Jun 1996 | |
| SB900-031R1 | Swashplate Modification, Inner Retainer Plate Replacement | 01 Jul 1996 | |
| SB900-030R1 | Swashplate Bearing Installation Preload, One-Time Inspection | 22 May 1996 | |
| SB900-029 | NOTAR® Fan Diffuser Retention Fastener Inspection | 06 Sep 1996 | |
| SB900-028R1 | Swashplate Bearing, One-Time Inspection | 04 May 1996 | |
| SB900-027 | Rigging Inspection of VSCS Linkage | 09 May 1996 | |
| SB900-026 | Link Assembly, Drive - Scissors, One-Time Inspection | 09 Apr 1996 | |
| SB900-025 | Ignition Circuit Breaker Replacement | 09 May 1996 | |
| SB900-024 | Electronic Engine Control (EEC) Replacement | 22 Apr 1996 | |
| SB900-023 | Thruster Rotating Cone/Control Bearings Modifications | 25 Apr 1996 | |
| SB900-022 | V _{NE} Card and Support Installation | 09 May 1996 | |
| SB900-021R1 | Endplate Spar Tube (Vertical Stabilizer) Greasing Procedure | 03 Jan 1997 | |
| SB900-020R1 | High Puncture-Resistant Fuel Cell Modifications (Fuel Boost Pump Flanges and Rollover Valves) (Ref. Mod MD9009500013) | 01 Jul 1996 | |
| SB900-019 | Pitot Tube Replacement | 12 Mar 1996 | |
| SB900-018R1 | Lateral Anti-Torque - Drive Link Assembly Replacement | 24 May 1996 | |
| SB900-017R2 | Battery Warm Disable Relay Installation and Fuel Quantity Power Moved to Essential Bus (Modify A610 Panel From 900E2750610-107 to -113) | 16 Dec 1996 | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821

| Service Bulletins (Cont.) | | | |
|----------------------------------|--|---------------------------|---|
| Publication Number | Publication Title | Issue/Reissue Date | Applicable Airworthiness Directive |
| SB900-016R2 | Aft Cabin Heat Modifictaion and Guard Installation | 28 Dec 1996 | |
| SB900-015 | Aft Cabin Heat Modification | 24 May 1996 | |
| SB900-014 | Cabin Door D-Ring Replacement | 23 Feb 1996 | |
| SB900-013 | Torque Verification of Blade Retention Bolts | 12 Jan 1996 | |
| SB900-012R1 | Condenser Scoop Installation | 12 Jul 1997 | |
| SB900-011 | Vent Air Scoop Installation | 05 Feb 1996 | |
| SB900-010 | Fuel Metering Unit (FMU) Manual Mode Deceleration Check | 14 Feb 1996 | |
| SB900-009 | Heater Limitation Placard Installation | 14 Dec 1995 | |
| SB900-008 | Forward Fuel Vent Modification (Ref. Mod MD9009500001) | 14 Dec 1995 | |
| SB900-007R1 | Service Instruction For Cockpit and Cabin Door Modifications (Ref. Mod MD9009500008) | 14 Dec 1995 | |
| SB900-006 | Application of Collective Control Index Mark | 19 Jul 1995 | |
| SB900-005 | Replacement of Generator Control Units (GCU's) | 19 Jul 1995 | |
| SB900-003R1 | Anti-Torque Directional Control Actuator Replacement | 29 Jan 1996 | |
| SB900-002R1 | Copilot Collective Stick Removal Restriction | 22 Dec 1995 | |
| SB900-001R5 | Flexbeam Inspection | 27 Aug 1999 | |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.
4555 East McDowell Road
Mesa, Arizona 85215-9734

MODEL MD900® HELICOPTERS (MD EXPLORER®) TECHNICAL BULLETIN INDEX

| Technical Bulletins | | |
|---------------------|--|--------------------|
| Publication Number | Publication Title | Issue/Reissue Date |
| TB900-033 | Modification Of Roof Rib Bracket | 05 Feb 2010 |
| TB900-032 | VSCS Test Box | 02 Feb 2010 |
| TB900-031 | MD900 (902 Configuration) PW206E to PW207E Engine Conversion Modification | 02 Nov 2009 |
| TB900-030 | Supplemental Fuel System Installation | 20 Feb 2008 |
| TB900-029 | Upper Deck Air Conditioning System Installation | 09 Feb 2008 |
| TB900-028 | MD900 (900 Configuration To MD900 (902 Configuration With PW207E Engines) Change | 20 Dec 2007 |
| TB900-027R1 | Electrical Noise Suppression Modification | 06 Mar 2008 |
| TB900-026 | Supplemental Fuel Cell (Check Valve) Modification | 27 May 2003 |
| TB900-025R2 | Generator Cooling Modification | 14 Aug 2003 |
| TB900-024 | Cabin Door Modification | 23 Apr 2003 |
| TB900-023 | Oil Cooler Inlet Duct Modification | 27 Jan 2002 |
| TB900-022 | Rain Gutter Modification | 17 Jun 2002 |
| TB900-021 | Cabin Window Emergency Release Cover Modification | 26 Feb 2002 |
| TB900-020R2 | Removable Copilot Controls Modification | 02 May 2002 |
| TB900-019 | Range Extender Modification | 30 Aug 2000 |
| TB900-018R2 | Dual Essential Bus Relays Modification | 23 Aug 2001 |
| TB900-017 | Heat/Defog Shutoff Valve Upgrade Modification | 26 Jul1999 |
| TB900-016R2 | Dual Pilot to Single Pilot Control Conversion | 16 Nov 2000 |
| TB900-015 | Windscreen Wipers -103 Installation | 17 Jun1999 |
| TB900-014R4 | JAR OPS-3 Modification | 13 Nov 2001 |
| TB900-012R1 | Fire Extinguishing System Installation | 09 Feb 2000 |
| TB900-011 | Landing/Hover Light Relocation Modification | 17 Mar 1999 |
| TB900-010R1 | Increased One Engine Inoperative (OEI) Torque Limit Modification | 13 Dec 2001 |
| TB900-009 | Modification Instructions for Optional 27 Ampere Hour Battery | 20 Nov 1998 |
| TB900-008 | NAS1919 and NAS1921 Alternate Fastener with Drive Anvil | 06 Nov 1998 |
| TB900-007R1 | Main Rotor Blade Root End Abrasion Tape | 14 Feb 2001 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



| Technical Bulletins (Cont.) | | |
|------------------------------------|---|---------------------------|
| Publication Number | Publication Title | Issue/Reissue Date |
| TB900-006R1 | Main Rotor Blade Pitch Case Abrasion Tape | 14 Feb 2001 |
| TB900-005 | Heat/Defog Upper Deck Through Fitting Modification | 12 Jan 1998 |
| TB900-004 | Modification Instructions for NACA Inlet Assembly Installation | 11 Nov 1997 |
| TB900-003R2 | Tub Shell (Fuselage) Inspection Panels, Modification to Install | 22 Sep 2009 |
| TB900-002 | Alternate Nutplate Installation | 11 Nov 1997 |
| TB900-001 | VSCS Actuator Mounting Bracket Repair | 11 Nov 1997 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.
 4555 East McDowell Road
 Mesa, Arizona 85215-9734

**MODEL MD900® HELICOPTERS
 (MD EXPLORER®)
 SERVICE LETTER INDEX**

| MD-900 Service Letters | | |
|-------------------------------|---------------------------|---|
| Publication Number | Issue/Reissue Date | Publication Title |
| SL900-069 | 26 Jan 2010 | Bendix/King by Honeywell – Wingman Services: Database Downloads and EGPWS Updates |
| SL900-068 | 14 Jan 2010 | Thruster Assembly Washer Modification |
| SL900-067 | 09 Nov 2009 | Landing Gear Damper Assembly And Sealing Compound |
| SL900-066 | 27 Oct 2009 | Main Rotor Drive Plate O-Ring Packing |
| SL900-065 | 26 Aug 2009 | Installation of Engine Ground Studs |
| SL900-064 | 29 Jul 2009 | Main Rotor Balde Retention Bolt |
| SL900-063 | 24 Jun 2009 | Main Rotor Balde Retention Bolt Check |
| SL900-062 | -- | Not Issued |
| SL900-061 | 13 Feb 2009 | IIDS Maximum Number Limits |
| SL900-060R1 | 02 Jun 2008 | Better Oil Transmission Hoses |
| SL900-059 | 04 Jan 2008 | Honeywell EFIS IFR STC (SR00436WI-D) |
| SL900-058 | 27 Dec 2007 | NOTAR® Fan Tension-Torsion Strap Replacement |
| SL900-057 | 30 Nov 2007 | Collective Control Position Transducer Linkage |
| SL900-056 | 19 Jun 2007 | Main Rotor Blade Retention Bolt Check |
| SL900-055 | 13 Feb 2007 | Thruster Control Cables |
| SL900-054 | 06 Feb 2008 | Main Rotor Hub Fretting Buffer and O-Ring Packing |
| SL900-053 | 13 Sep 2005 | Anti-Torque Control Pedal Separation |
| SL900-052 | 29 Mar 2005 | Calculation Of One Engine Inoperative (OEI) Excursions Cumulative Log Time For 900A3720002-113 and 900A3720002-121 IIDS |
| SL900-051 | 17 Sep 2003 | Availability of MDHI Publications in Electronic Format |
| SL900-050 | 21 Mar 2003 | Integrated Instrumentation Display System (IIDS) Mod 3 |
| SL900-049 | 10 Dec 2002 | Prolonging the Life of the Integrated Instrument Display (IIDS) |
| SL900-048 | 17 Sep 2002 | Availability of New Engine Alignment Tool |
| SL900-047 | 02 Mar 2001 | New Standard Warranty Statement |
| SL900-045 | 29 Jun 2000 | Anti-Torque Fan Inlet Screen |
| SL900-044R1 | 26 Jun 2000 | Availability of Federal Aviation Administration Supplemental Type Certificates for MD Helicopters |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD-900 Service Letters (Cont.)

| Publication Number | Issue/Reissue Date | Publication Title |
|--------------------|--------------------|---|
| SL900-043 | 23 May 2000 | Availability of Federal Aviation Administration Airworthiness Directives Affecting MD Helicopters |
| SL900-042R1 | 14 Jan 2002 | Integrated Instrumentation Display System (IIDS) |
| SL900-041 | 19 Feb 1999 | Transfer of Ownership |
| SL900-040 | 13 Oct 1998 | Structural Load Limits of MD900 Fuselage Handles |
| SL900-038 | 13 Feb 1998 | Service Bulletin/Letter Designation |
| SL900-036R1 | 10 Mar 2000 | Electronic Engine Control - P&WC S.B. 28111 |
| SL900-035 | 26 Jun 1997 | Vent System Air/Duct Addition Air Outlets Installation (Ref. Mod 9009500003) |
| SL900-033 | 14 May 1997 | Aft Jack Pad Access Hole |
| SL900-032 | 05 May 1997 | Strobe Light Circuit Breaker Change |
| SL900-029 | 17 Mar 1997 | Baggage Compartment Closeout Panel Installation for Utility Interiors |
| SL900-025R1 | 23 Jan 1998 | Cabin Door Handle Installation |
| SL900-024 | 03 Jan 1997 | Baggage Door Window Installation |
| SL900-021R2 | 09 Nov 2009 | Four Point Passenger Restraint System |
| SL900-020R1 | 03 Jan 1997 | Hoist Inspection Hole Installation |
| SL900-019 | 20 Dec 1996 | Station 203 Ground Handling Hardware |
| SL900-018 | 18 Dec 1996 | Pedal Friction Hardware Option |
| SL 900-016 | 14 Aug 1996 | Secondary Oil Ejector Modification |
| SL 900-015 | 08 Jul 1996 | Fastener Hardware Upgrade |
| SL 900-014 | 21 May 1996 | Trim Actuator Replacement |
| SL 900-013R1 | 21 Mar 1997 | Alternate Floor Panel Hardware Usage |
| SL 900-011 | 05 Apr 1996 | Cockpit Door Latch Mechanism Modification |
| SL 900-010 | 19 Jan 1996 | Integrated Instrumentation Software Upgrade |
| SL 900-009 | 06 Dec 1995 | Directional Control Inputs Information |
| SL 900-007 | 22 Sep 1995 | Aircraft Modification Limitations and STC Installations |
| SL 900-006 | 11 Nov 1995 | Pedal Return Springs |
| SL 900-005 | 11 Nov 1995 | Improved Rig Pin Access FOD Covers |
| SL 900-003 | 15 May 1995 | Ground Handling Precautions |
| SL 900-002R1 | 22 Jun 2000 | P&WC Publications Distribution Information |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



MD Helicopters, Inc.
 4555 East McDowell Road
 Mesa, Arizona 85215-9734

**MODEL MD900® HELICOPTERS
 (MD EXPLORER®)**

CANCELED PUBLICATIONS INDEX

| Canceled Rotorcraft Maintenance Manual Instructions (RMM) | | |
|--|----------------------|--|
| Publication Number | Date Canceled | Publication Title |
| CSP-900CMM-5 STC1 | 27 Sep 2002 | 600# Rescue Hoist Kit (REF.: P/N 900FG000004) (Superseded by CSP-900RMM-2, Rev 17. CSP-900RMM-3, Rev 9, CSP-900IPL-4, Rev 6) |
| CSP-900WIR-8 | 30 Jan 1998 | Aircraft Wiring Manual (Superseded by CSP-900RMM-3) |

| Canceled Rotorcraft Flight Manuals (RFM) | | |
|---|----------------------|---|
| Publication Number | Date Canceled | Publication Title |
| CSP-900RFM-1 | 26 Feb 2003 | Rotorcraft Flight Manual (900 Config/PW206A) (Superseded by CSP-900RFM206A-1). |
| CSP-900RFM-S0 | 26 Feb 2003 | Belgian Helicopters, RFM Supplement to CSP-900RFM-1 (900 Config w/ PW206A) (Superseded by CSP-900RFM206A-S1). |
| CSP-900RFM-S1 | 12 Mar 2003 | 6500 LB Gross Weight Operations Supplement, RFM Supplement to CSP-900RFM-1 (900 Config w/ PW206A Serial Number specific) (Superseded by CSP-900RFM206A-S1). |
| CSP-900RFM-S2 | 12 Mar 2003 | Takeoff & Landing Operations (JAR OPS), RFM Supplement to CSP-900RFM-1 (900 Config w/ PW206A) (Superseded by CSP-900RFM206A-S2). |
| CSP-900ERFM-1 | 12 Mar 2003 | Rotorcraft Flight Manual (900 Config/PW206E , SN 0041 & 0042 Only) (Superseded by CSP-900RFM206E-1). |
| CSP-902RFM-1 | 12 Mar 2003 | Rotorcraft Flight Manual (902 Config/PW206E) (Superseded by CSP-902RFM206E-1). |
| CSP-900RFM207E-S1 | N/A | Not Issued |
| CSP-900RFM206A-S1 | 21 Aug 2007 | Increased Gross Weight Operations. Data now included in CSP-900RFM206A-1 |
| CSP-900RFM207E-S2 | 21 Aug 2007 | Increased Gross Weight Operations. Data now included in CSP-900RFM207E-1 |
| CSP-902RFM207E-S1 | 21 Aug 2007 | Increased Gross Weight Operations. Data now included in CSP-902RFM207E-1 |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821



Canceled Service Bulletins

| Publication Number | Date Canceled | Publication Title |
|--------------------|---------------|--|
| SB900-004 | 22 Apr 1996 | Electronic Engine Control (EEC) Replacement (Superseded by SB900-024) |

Canceled Technical Bulletins

| Publication Number | Date Canceled | Publication Title |
|--------------------|---------------|-------------------|
| TB900-013 | | Not Issued |

Canceled Service Letters

| Publication Number | Date Canceled | Publication Title |
|--------------------|---------------|--|
| SL 900-001 | 26 Jan 2004 | Chip Light Indication Reporting |
| SL 900-004 | 27 Jan 2004 | Engine Starting |
| SL 900-008 | 28 Jan 2004 | Alternate Cyclic Grip |
| SL 900-012 | 29 Jan 2004 | IIDS Lamp Replacement |
| SL 900-017 | 29 Jan 2004 | IIDS Phase 2 Implementation |
| SL900-022R2 | 29 Jan 2004 | Main Rotor Blade Root End Abrasion Tape (Superseded by TB900-007) |
| SL900-023R1 | 17 Jun 2002 | Rain Gutter Modification (Superseded by TB900-022) |
| SL900-026 | 26 Feb 2002 | Cabin Window Emergency Release Cover (Superseded by TB900-021) |
| SL900-027R1 | 30 Jan 2004 | Main Transmission Retrofit Program |
| SL900-028R1 | 30 Jan 2004 | Autopilot/SAS Procedural Changes for Bendix/King IFR and VFR Avionics/KFC 900 Flight Control Systems |
| SL900-030 | 27 Jan 2002 | Optional Installation of Access Holes to RH and LH Oil Cooling Inlet Ducts (Superseded by TB900-023) |
| SL900-031 | 30 Jan 2004 | Simulated EEC Failures Manual Mode Training |
| SL900-034 | 30 Jan 2004 | Non-Rotating Swashplate Life Extension |
| SL900-037 | 19 Jan 2004 | Primary Exhaust Nozzle Inspection |
| SL900-039 | 02 Feb 2004 | Main Rotor Hub Inspection (Superseded by SB900-065) |
| SL900-046R1 | 29 Oct 2001 | Approved Electronic Engine Control (EEC) and Integrated Instrument Display (IIDS) Part Numbers |

If the date of this publications index is older than six months, contact MDHI Commercial Technical Publications Order Desk to obtain a current publications index. TELE: 1-800-388-3378 or 480-346-6373, FAX: 480-346-6821