

**CESSNA AIRCRAFT COMPANY  
MODEL 300 SERIES  
CONTINUED AIRWORTHINESS PROGRAM**

**TITLE**            **Pilot / Copilot Shoulder Harness Reel and Support**

| <b>MODEL</b>      | <b>EFFECTIVITY</b>                  | <b>INSPECTION COMPLIANCE</b> |                   |
|-------------------|-------------------------------------|------------------------------|-------------------|
| T303              | T30300001 Thru T30300315            |                              |                   |
| 335               | 335-0001 Thru 335-0065              |                              |                   |
| 336               | 633, 636, 336-0001 Thru<br>336-0195 | <b>INITIAL</b>               | <b>2 YRS</b>      |
| 337 Thru P337H-SP | 337-0002 Thru 33701955              |                              |                   |
| T337G Thru P337H  | P3370001 Thru P3370356              | <b>REPEAT</b>                | <b>2 YRS</b>      |
| F337E/FT337F      | F3370001 Thru F33700055             |                              | <b>Thereafter</b> |
| FT337GP/FT337HP   | FP33700001 Thru FP33700023          |                              |                   |
| 340 Thru 340A     | 340-0001 Thru 340A1817              |                              |                   |

**PURPOSE**

To ensure shoulder harness reels function properly and their attachment is secure.

**INSPECTION INSTRUCTIONS**

1. Remove inertia reel in accordance with the applicable Service Manual.
2. Inspect inertia reel to ensure proper function and secure attachment to under structure.
3. Inspect under structure for cracks and corrosion.
4. Reinstall inertia reel in accordance with the applicable Service Manual.

**ACCESS/LOCATION**

Under Royalite cover

**DETECTABLE CRACK SIZE**

N/A

**INSPECTION PROCEDURE**

Refer to inspection instructions above.

**REPAIR/MODIFICATION**

Repair or replace as required in accordance with the applicable Service Manual.

**COMMENTS**

Ref: MEB92-8