SERVICE BULLETIN

MANDATORY MANDATORY MANDATORY

INSPECTION – TAIL ROTOR TRANSMISSION ASSEMBLY, P/N 369A5400

1. PLANNING INFORMATION

A. MODELS AFFECTED: **

B. PREFACE: **

** The terms and conditions defined under ”Models Affected”, ”Time of Compliance”, ”Preface” and the remainder of Service Information Notice No. HN–1.1 dated October 6, 1969 are not affected by this addendum except for the following:

A supplemental list of tail rotor transmission serial numbers is added (See page 2). If tail rotor gearbox installed on aircraft or in spares inventory is included on either the original or supplemental list of serial numbers, the gearbox must be replaced.

C. TIME OF COMPLIANCE: **

D. FAA APPROVAL:

FAA/DOA WE–1 APPROVED

E. REFERENCE:

500 Series – Basic Handbook of Maintenance Instructions, Revised 15 May 1969

369HM Maintenance Manual Supplement to U.S. Army Maintenance Manuals TM55–1520–214–20 and TM55–1520–214–35, Issued 1 April 1968.

(I) Denotes portion of text added or revised.

Copyright 1999-2000 by MD Helicopters Inc. This document may be reproduced and distributed provided no fee is charged, the text is not modified, and this copyright notice is included.

SERVICE BULLETIN

MANDATORY MANDATORY MANDATORY

SUPPLEMENTAL LIST – TAIL ROTOR TRANSMISSION
P/N 369A5400 SERIAL NUMBERS

19	3825
19	3831
19	3844
19	3854
19	3883
19	3885
19	3886
19	3888
19	3889
19	3891
29	3906
29	3907
39	3923
39	3924
39	3925
39	3939
39	3940
39	3946
39	3948
39	3974
39	3975
39	3977
39	3979
39	3981
39	3982
39	3983
39	3984
39	3985
39	3986
39	3987
39	3988
39	3989
59	4012
59	4015
59	4016
59	4017
98	3199
98	3201
98	3205
98	3254
98	3263
98	3287
108	3436
108	3503
108	3513
108	3519
118	3603
118	3605
118	3606
118	3607
118	3608
118	3609
118	3610
118	3611
118	3612
118	3622
118	3642
128	3690
128	3697
128	3782
128	3806

Copyright 1999-2000 by MD Helicopters Inc. This document may be reproduced and distributed provided no fee is charged, the text is not modified, and this copyright notice is included.

MANDATORY MANDATORY MANDATORY