



SERVICE MANUAL CHANGE NOTICE

SMCN # 77-17

REFERENCE MANUAL NUMBER: As Noted Below

DATE: July 25, 1977

MANUAL TITLE: Super Skymaster (65 thru 73), Skymaster (74 thru 77) and Pressurized Skymaster(73 thru 77)

TO: All Zones and Multi-engine

FROM: CUSTOMER SERVICES DEPARTMENT

CORRECT YOUR SERVICE MANUAL AS SHOWN BELOW.

MANUAL NUMBER	PAGE NUMBER	PARAGRAPH NUMBER	DESCRIPTION OF CHANGES
D2506-4-13	11-14	11-9D	Due to inaccessability of the hose and clamp when installing the inboard fuel tank the following note is to be added to the applicable Service Manuals:
D2500-13	11-28	11-63	
D2516-5-13	11-3	11-10	
			<p style="text-align: center;">NOTE</p> <p>To provide access to the hose and clamp when installing inboard fuel tank, drill two (2) .75 inch diameter holes in both lower wing skins. Locate first hole .85 inch inboard of wing station 55.50 and 16.10 inches fwd. of the rear wing spar. Locate second hole .63 inches inboard of wing station 55.50 and 5.65 inches aft of the front spar. Install CM2692-24-1S plug buttons in access holes and paint to match lower wing skin paint.</p>