



SERVICE LETTER

HL-99
DL-70
EL-21
FL-11

DATE: 15 JUNE 1987
PAGE 1 OF 1

TO: All owners and operators of McDonnell Douglas Helicopter Company (MDHC) 369 Series helicopters.

UNAUTHORIZED DISTRIBUTION OF MAIN ROTOR HUB OVERHAUL MANUAL.

MDHC has learned that an unauthorized copy of Publication No. CSP-O73IL, Main Rotor Hub (P/N 369D21200-711) overhaul procedures may have been inadvertently delivered to some owners and operators of MDHC helicopters.

This manual is not approved for general usage and should be destroyed. MDHC does not approve overhaul of the main rotor hub assemblies outside of MDHC or MDHC Approved Overhaul Licensees.

A handwritten signature in black ink that reads 'Cary Brown'.

Cary Brown, Manager,
Product Support Department
McDonnell Douglas