

**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. HL-47

DATE 24 Dec 1976

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: IMPROVED ENGINE AIR FILTER ASSEMBLY FOR PARTICLE
SEPARATOR FILTER KIT

MODELS AFFECTED: All 500 Model 369H Series Helicopters equipped with
PN 369H90148 Basic and -501 Particle Separator Filter Kit

Reference

500 Series - Basic HMI, Issued 1 October 1972; Revision No. 6, 1 November 1976

500 Series - HMI Appendix A, Issued 1 October 1972; Revision No. 4, 15 Dec 1974

Hughes Service Information Notice No. HN-96 dated 10 May 1976

Installation Instructions - Engine Air Particle Separator Filter Installation Kit,
PN 369H90148 Basic or -501, Revised 15 May 1976

A new 369H90152-3 engine air filter assembly for the particle separator kit is now available. The new -3 filter configuration incorporates outlet tubes designed with locking collars to provide positive attachment to the filter housing, thus eliminating the need for the 369A90157 aft screen assembly specified in the above referenced Hughes Notice No. HN-96 and Particle Separator Kit Installation Instructions.



Edward Koch, Manager
Customer Service Department
Hughes Helicopters

Customer Service Department - Hughes Helicopters - Culver City, California