



Manual: CSP-COM-5, Component Overhaul Manual
Models: 369D/E/F/FF - 500/600N Helicopters
Issued: 17 August 1991
Revision 17: 28 July 2007
TR09-002: 24 August 2009

FILING INSTRUCTIONS:

1. Before you put this temporary revision in the manual, make sure the manual contains all the revisions from before. Look at the last revision List of Effective Pages.




Do not put this temporary revision in the manual, if the manual does not contain all the revisions from before.

2. To include this temporary revision in the manual, remove old pages and put in new pages as shown below.

Temporary Revision Number/Date	Section	Page	Page Revision
TR07-001/14 November 2007	63-20-00	517 and 518	TR 07-001
		305 and 306	TR 07-001
		401 and 402	TR 07-001
		511 thru 514	TR 07-001
		705 thru 708	TR 07-001
	63-25-10	509 and 510	TR 07-001
TR08-001/02 October 2008	63-25-20	709	Revision 17
		710	TR08-001
TR09-001/25 March 2009	63-25-10	707 thru 709	TR09-001
		710	Revision 17
		905	TR09-001
		906	Revision 4
		1003 thru 1005	TR09-001
		1006	Revision 14
TR09-002/24 August 2009	63-10-15	509	TR09-002
		510	Revision 13

This Page Intentionally Left Blank



NOTE: USE TOOL (4, TABLE 901) FOR INSPECTING OF SPRAG WINDOW WEAR.

H63-1034B

Figure 505. Inspection Requirements of 369F5456 Sprag Assembly

This Page Intentionally Left Blank